



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
051233 051233N	INSPECT BATTERY (CONCORDE)			RG-380E/44 40398444	MTH 04-Feb-2011 HRS 4942.2 LDG 5335	4942.2	12 600		29-Feb-2012 5542.2	6 m 19 d 561.2
5-12-01 051204	PHASE 1 INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
5-12-02 051205	PHASE 2 INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
5-12-03 051206	PHASE 3 INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
5-12-04 051207	PHASE 4 INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
5-12-05 051210	PHASE 5 INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		36 1200		30-Jun-2013 6121	22 m 20 d 1140
5-12-0B 051218	PHASE B	SEE			MTH 25-Apr-2011 HRS 4958.3 LDG 5359		150		5108.3	127.3
5-12-12 051003	PHASE 12 INSPECTION	DRO			MTH 20-May-2004 HRS 4506 LDG 4820		600 600		5106 5420	125 29
5-12-15 052013 : B	PHASE 15 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		10000		10000	5019
5-12-16 052013 : C	PHASE 16 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		10000		10000	5019
5-12-17 052013	PHASE 17 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		10000		10000	5019
5-12-18 051005	PHASE 18 INSPECTION	SEE			MTH 23-Jun-2011 HRS 4968.8 LDG 5371		12		30-Jun-2012	10 m 20 d
5-12-20	PHASE 20 INSPECTION				MTH 12-Sep-1980		24			
B341001 COPILOT 051006 : R	CALIBRATION TEST ALTIMETER FAR 91.411: PHASE 20 INSPECTION	SEE		C661072-0102 1045011139	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B341001 LEFT 051223 : L	CALIBRATION TEST AIRSPEED INDICATOR FAR 91.411: PHASE 20 INSPECTION	SEE		AW2837AC03 W978H	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B341001 NO. 1 051007	CALIBRATION TEST AIR DATA COMPUTER FAR 91.411: PHASE 20 INSPECTION	SEE		4013241-901 6070250	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B341001 PILOT 051005 : L	CALIBRATION TEST ALTIMETER FAR 91.411: PHASE 20 INSPECTION	SEE		4016341-905 81032041	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B341001 RIGHT 051223 : R	CALIBRATION TEST AIRSPEED INDICATOR FAR 91.411: PHASE 20 INSPECTION	SEE		C661063-0103 46	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B341003 LEFT 051220 : L	LEAK TEST STATIC SYSTEM FAR 91.411 : PHASE 20 INSPECTION	SEE			MTH 25-Apr-2011 HRS 4958.3 LDG 5359		24		30-Apr-2013	20 m 20 d



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B341003 RIGHT <i>051220 : R</i>	LEAK TEST STATIC SYSTEM FAR 91.411 : PHASE 20 INSPECTION	SEE			MTH 25-Apr-2011 HRS 4958.3 LDG 5359		24		30-Apr-2013	20 m 20 d
B345001 NO. 1 <i>051221 : R</i>	CALIBRATION TEST ATC TRANSPONDER FAR 91.413: PHASE 20 INSPECTION	SEE		622-1270-001 8486	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
B345001 NO. 2 <i>051221</i>	CALIBRATION TEST ATC TRANSPONDER FAR 91.413: PHASE 20 INSPECTION	SEE		622-1270-001 9178	MTH 25-Apr-2011		24		30-Apr-2013	20 m 20 d
5-12-22	PHASE 22 INSPECTION	SEE			MTH 25-Apr-2011 HRS 4958.3 LDG 5359		36			
B326003 <i>051227</i>	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22 INSPECTION	SEE		23111321 7031632	MTH 25-Apr-2011 HRS 4958.3 LDG 5359		36		30-Apr-2014	32 m 20 d
5-12-23	PHASE 23 INSPECTION				MTH 12-Sep-1980		60			
B262002 AFT <i>121001 : A</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23 INSPECTION	MYF		30401102 B14282	MTH 02-Jul-2007 HRS 4741		60		31-Jul-2012	11 m 21 d
B262002 FORWARD <i>121001 : F</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23 INSPECTION	CRQ		30401102 B13366	MTH 27-Apr-2009 HRS 4854		60	4	31-Dec-2013	28 m 21 d
5-12-24 <i>052013 : A</i>	PHASE 24 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		10000		10000	5019
5-12-26	PHASE 26 INSPECTION				MTH 12-Sep-1980		120			
B350005 <i>051226</i>	HYDROSTATIC TEST OXYGEN CYLINDER : PHASE 26 INSPECTION	MYF		ZC371 4228	MTH 21-Nov-2008 HRS 4831		60		30-Nov-2013	27 m 20 d
5-12-34	PHASE 34 INSPECTION	SEE			MTH 23-Jun-2011 HRS 4968.8 LDG 5371		6			
A262003 COCKPIT <i>051018 : F</i>	WEIGHT CHECK PORTABLE EXTINGUISHER : PHASE 34 INSPECTION	SEE		C352, Y-22196	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		6		31-Dec-2011	4 m 21 d
5-12-37 <i>052010</i>	PHASE 37 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		5000		5000	19
5-12-40 <i>052013 : E</i>	PHASE 40 INSPECTION (NOT CURRENTLY USED)	*CF			MTH 12-Sep-1980		A/R			
5-12-47	PHASE 47 INSPECTION				MTH 12-Sep-1980		144			
B262003 COCKPIT <i>051019 : F</i>	HYDROSTATIC TEST PORTABLE EXTINGUISHER : PHASE 47 INSPECTION	SEE		C352, Y-22196	MTH 31-Jan-2009		144		31-Jan-2021	113 m 21 d
5-12-49 <i>051210 : SJ</i>	PHASE 49 INSPECTION	MYF			MTH 18-Feb-2009 HRS 4842		36 1200		29-Feb-2012 6042	6 m 19 d 1061
5-12-50 <i>052013 : F</i>	PHASE 50 INSPECTION	MYF			MTH 18-Feb-2009 HRS 4842		36 1200		29-Feb-2012 6042	6 m 19 d 1061
5-12-52 <i>051252</i>	PHASE 52 INSPECTION	*CF			MTH 12-Sep-1980 HRS 0		5000		5000	19

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-53 051253	PHASE 53 INSPECTION	SEE			MTH 23-Jun-2011 HRS 4968.8 LDG 5371		12		30-Jun-2012	10 m 20 d
5-12-MA 0512MA	PHASE MA INSPECTION	*CF			MTH 12-Sep-1980 LDG 0		12000		12000	6609
5-12-MD 0512MD	PHASE MD INSPECTION	MYF			MTH 16-May-2006 HRS 4670 LDG 5004		5000		10004	4613
5-12-MF	PHASE MF INSPECTION				MTH 12-Sep-1980 HRS 0 LDG 0		224			
5-12-MG	PHASE MG INSPECTION				MTH 12-Sep-1980 HRS 0 LDG 0		425			
A324009	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") FOR AIRPLANES WITH AND USING THRUST REVERSERS. PHASE MG INSPECTION									
LEFT MAIN LANDING GEAR					MTH LDG		425		5743	352
A324009	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") FOR AIRPLANES WITH AND USING THRUST REVERSERS									
RIGHT MAIN LANDING GEAR					MTH LDG		425		5743	352
057110 E1 051208 : E1**L	MINOR INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
057110 E2 051209 : E2**R	MINOR INSPECTION	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		24 300		30-Jun-2012 5221	10 m 20 d 240
262037	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)									
AFT LEFT 262003 : AL				M13083-5 22333	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		72		30-Jun-2017	70 m 20 d
262038	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)									
AFT RIGHT 262003 : AR				M13083-5 12110	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		72		30-Jun-2017	70 m 20 d
262039	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)									
FORWARD LEFT 262003 : FL		CRQ		AE13083-5 808	MTH 27-Apr-2009 HRS 4854		120		30-Apr-2019	92 m 20 d
262040	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)									
FORWARD RIGHT 262003 : FR		CRQ		AE13083-5 808	MTH 27-Apr-2009 HRS 4854		120		30-Apr-2019	92 m 20 d
710010 E1 710001 : E1**L	OVERHAUL				MTH 15-Sep-1999 HRS 3695		3500	121	7074	2093
710010 E2 710001 : E2**R	OVERHAUL				MTH 10-Nov-1995 HRS 3430		3500		6930	1949
710020 E1 051001 : E1**L	HOT SECTION INSPECTION	EKB			MTH 15-Sep-1999 HRS 3695		1800	121	5374	393
710020 E2 051002 : E2**R	HOT SECTION INSPECTION	EKB			MTH 10-Nov-1995 HRS 3430		1800		5230	249

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
720010 E1	OIL ANALYSIS						A/R			
720010 E2	OIL ANALYSIS				MTH 12-Sep-1980		A/R			
725040 E1 <i>724707 : E1**L</i>	REPLACE HIGH TURBINE BLADES EKB				MTH 15-Sep-1999 HRS 3695		3500	121	7074	2093
725040 E2 <i>724707 : E2**R</i>	REPLACE HIGH TURBINE BLADES EKB				MTH 10-Nov-1995 HRS 3430		3500		6930	1949
792010 E1 <i>051003 : E1**L</i>	CHANGE OIL	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C			
792010 E2 <i>051004 : E2**R</i>	CHANGE OIL	SEE			MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION VALVE	MYF		27441482-06 8BA17	MTH 16-May-2006 HRS 4670		O/C	0		
212002 CABIN	AFT OVERHEAD BLOWER			23-9 667	MTH 26-Jun-1992 HRS 3222		O/C	2142		
212003	AIR INLET DOOR ACTUATOR	*CF		1H56-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
212005 LEFT CABIN	COOLING FAN	*CF		WS2107F30 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
212005 RIGHT CABIN	COOLING FAN	*CF		WS2107F30 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
212010	DOOR ACTUATOR MOTOR ASSEMBLY	*CF		9910059-3 5A3032 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
213001 CABIN	PRESSURE INDICATOR	*CF		3001J14 C668511-0102 15427	MTH 12-Sep-1980		O/C			
213002	PRESSURIZATION CONTROLLER	ZRH		130356-5 67-482	MTH 21-Apr-1989 HRS 2435		O/C	0		
213003 CABIN	RATE OF CLIMB INDICATOR	*CF		35060-1128 C668513-0101 W4687G	MTH 12-Sep-1980		O/C			
213005 LEFT CABIN	ALTITUDE LIMIT VALVE	*CF		9912055-1 102466-1 292845	MTH 12-Sep-1980		O/C			
213005 RIGHT CABIN	ALTITUDE LIMIT VALVE	*CF		9912055-1 102466-1 992765	MTH 12-Sep-1980		O/C			
213006	SAFETY OUTFLOW VALVE	ZRH		103576-13 707434	MTH 16-Feb-1988 HRS 2120		O/C	0		
213007	NORMAL OUTFLOW VALVE	ZRH		103576-12 19605	MTH 16-Feb-1988 HRS 2120		O/C	0		
213008	MANUAL DUMP VALVE	*CF		2101701-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
213009 LEFT	BLEED AIR FLOW CONTROL VALVE	*CF		9912109-1 225645-2 218	MTH 12-Sep-1980		O/C			
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE	*CF		9912109-1 225645-2 154	MTH 12-Sep-1980		O/C			
213013	PNEUMATIC RELAY	*CF		130358-1 79-828	MTH 12-Sep-1980		O/C			
215001	REFRIGERATION UNIT	*CF		9912069-21 738443-13 S1641	MTH 12-Sep-1980		O/C			
215002	ASPIRATOR AND FAN HOUSING	*CF		740730-2 SN-UNKNOWN	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215004	AIR CYCLE MACHINE	GOA		738384-8 48434	MTH 30-May-1991 HRS 3007		5000	0	8007	3026
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	BYPASS VALVE 9912069-1	ICT		754751-2 039814	MTH 14-May-1982 HRS 318		O/C	0		
215006	OVERHEAT SWITCH	*CF		746833-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
215007	GROUND OPERATION VALVE 9912068-3	*CF		225655 258	MTH 12-Sep-1980		O/C			
216001	CABIN TEMPERATURE SELECTOR	*CF		5518118-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
216002	TEMPERATURE CONTROL UNIT 9912069-22	ZRH		754661-5 L46600	MTH 14-Jul-1983 HRS 644		O/C	815		
216003	DUCT TEMPERATURE SENSOR 9912069-14	GJT		754691-1 SN-UNKNOWN	MTH 05-Jan-2000 HRS 3802		O/C	0		
216004	CABIN TEMPERATURE SENSOR 9912069-15	ZRH		754681-1 976820	MTH 08-May-1983		O/C			
216005	CENTRIFUGAL BLOWER 9912070-1	DRO		19A2338 104	MTH 10-Nov-2000 HRS 4001		O/C	0		
221008	AUTOPILOT COMPUTER SP-200	ZRH		4008519-911 091372	MTH 20-Jan-1983 HRS 464		O/C	6		
221009	AUTOPILOT CONTROLLER PC-500	*CF		4018639-901 070953	MTH 12-Sep-1980		O/C			
221010 AILERON	SERVO ACTUATOR SM-200	EKB		4006719-904 83109468	MTH 19-Dec-1994 HRS 3393		O/C	0		
221010 ELEVATOR	SERVO ACTUATOR SM-200	GJT		4006719-904 86012444	MTH 05-Jan-2000 HRS 3802		O/C	148		
221010 RUDDER	SERVO ACTUATOR SM-200	*CF		4006719-906 024781	MTH 12-Sep-1980		O/C			
232002 NO. 2	VHF COMMUNICATION ANTENNA 9912084-1	*CF		VF10-108-1 683	MTH 12-Sep-1980		O/C			
232003 NO. 1	VHF COMMUNICATION ANTENNA LTN			VFS10-90-5 2551	MTH 04-Mar-1991 HRS 2965		O/C	0		
232010 NO. 1	TOP COMMUNICATION TRANSCEIVER VHF-21A	KBI		622-6389-011 6687	MTH 10-Nov-1995 HRS 3430		O/C	0		
232010 NO. 2	BOTTOM COMMUNICATION TRANSCEIVER VHF-20A	*CF		622-1879-002 10601	MTH 12-Sep-1980		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232011	COMMUNICATION CONTROL	DRO		1U434-001 T729B	MTH 16-Nov-2001 HRS 4205		O/C	0		
235001 LEFT	AUDIO AMPLIFIER	DRO		1630-1 523	MTH 17-Jun-2002 HRS 4324		O/C	4748		
235001 RIGHT	AUDIO AMPLIFIER	*CF		1630-1 713	MTH 12-Sep-1980		O/C			
235003 CABIN	SPEAKERS	*CF		48FU2103 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
235003 COCKPIT	SPEAKERS	*CF		48FU2103 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
235006 LEFT	TELEX HEADSET	*CF		62629-00 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
235006 RIGHT	TELEX HEADSET	*CF		62629-00 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
242001 NO. 1	AC INVERTER	LGB		PC15H 1092	MTH 20-Feb-2004 HRS 4478		O/C	4478		
242001 NO. 2	AC INVERTER	LGB		PC15H 1235	MTH 20-Feb-2004 HRS 4478		O/C	0		
242002	AC FAIL MONITOR	*CF		1371-1 535	MTH 12-Sep-1980		O/C			
243001 NO. 1	ENGINE STARTER/GENERATOR	SEE		23080-001-1 381	MTH 12-Feb-2009 HRS 4837		1000	0	5837	856
243001 NO. 2	ENGINE STARTER/GENERATOR	SEE		23080-001-1 4192	MTH 04-Feb-2011 HRS 4942.2 LDG 5335		1000	0	5942.2	961.2
243003 LEFT	GENERATOR CONTROL UNIT	MYF		51509-006BR 2382	MTH 10-Oct-2007 HRS 4767		O/C	0		
243003 RIGHT	GENERATOR CONTROL UNIT	MYF		51509-006BR 1383MA	MTH 10-Oct-2007 HRS 4767		O/C	26		
PLEASE NOTIFY CESCOM OF MANUFACTURE DATE, TIME ON COMPONENT, OR SERIAL NUMBER.										
243004 LEFT	AMMETER	*CF		C662501-0102 2936	MTH 12-Sep-1980		O/C			
243004 RIGHT	AMMETER	*CF		C662501-0102 2895	MTH 12-Sep-1980		O/C			
243005	VOLTMETER	*CF		C662502-0101 854	MTH 12-Sep-1980		O/C			
243007	BATTERY	SEE		RG-380E/44 40398444	MTH 04-Feb-2011 HRS 4942.2 LDG 5335		O/C	0		
BATTERY SHOULD BE REPLACED EVERY 60 MONTHS OR 5000 HOURS PER CONCORDE BATTERY MANUAL.										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243008	BATTERY TEMPERATURE MODULE	*CF		1529-1 359	MTH 12-Sep-1980		O/C			
243009	BATTERY TEMPERATURE GAUGE	ZRH		1229-1 808	MTH 19-Dec-1986 HRS 1853		O/C	0		
244001 K11	400 AMP RELAY	*CF		AN3380-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
244001 K12	400 AMP RELAY	*CF		AN3380-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
244001 K13	400 AMP RELAY	*CF		AN3380-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
244001 K1	400 AMP RELAY	*CF		AN3380-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
244001 K7	400 AMP RELAY	*CF		AN3380-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
244001 K8	400 AMP RELAY	ROM		AN3380-1 SN-UNKNOWN	MTH 30-May-1984 HRS 942		O/C	0		
245001 CENTER	5 VOLT LIGHT DIMMER	GJT		1505-1 2417	MTH 07-Jun-2000 HRS 3879		O/C	1981		
245001 LEFT	5 VOLT LIGHT DIMMER	ZRH		1505-1 1997	MTH 14-Jul-1983 HRS 644		O/C	0		
245001 RIGHT	5 VOLT LIGHT DIMMER	PBI		1505-1 1551	MTH 13-Apr-1981 HRS 117		O/C	0		
251001 LEFT	INERTIA REEL	*CF		CM4033 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
251001 RIGHT	INERTIA REEL	*CF		CM4033 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
256009 344009	EMERGENCY LOCATER TRANSMITTER ANTENNA	GJT		110-340 3081934	MTH 19-Jan-2004 HRS 4473		O/C	0		
256019 344008	EMERGENCY LOCATER TRANSMITTER	DRO		453-5002 05102	MTH 20-May-2004 HRS 4506		O/C	33		
256025 344010	EMERGENCY LOCATER TRANSMITTER BATTERY	MYF REV-P		452-0133 N/A	MTH 11-Jun-2008 HRS 4804	2	60	0	31-Aug-2013	24 m 21 d
261001 NO. 1 ENGINE	FIRE DETECTION SENSOR	9912036-3	*CF	244-18882 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
261001 NO. 2 ENGINE	FIRE DETECTION SENSOR	9912036-3	*CF	244-18882 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
261002 NO. 1 ENGINE	FIRE DETECTION CONTROL	9912036-2	*CF	377-02808 951073	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
261002 NO. 2 ENGINE	FIRE DETECTION CONTROL 9912036-2	*CF		377-02808 951072	MTH 12-Sep-1980		O/C			
262001 AFT	ENGINE FIRE EXTINGUISHER 9912048-2	MYF		30401102 B14282	MTH 02-Jul-2007 HRS 4741		O/C	126		
262001 FORWARD	ENGINE FIRE EXTINGUISHER 9912048-2	CRQ		30401102 B13366	MTH 27-Apr-2009 HRS 4854		O/C	0		
262002 COCKPIT	PORTABLE EXTINGUISHER			C352, Y-22196	MTH 16-Dec-2010 HRS 4935.5 LDG 5324		O/C	0 0 0		
262003 AFT LEFT	ENGINE FIRE EXTINGUISHER CARTRIDGE SEE			M13083-5 22333	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		72		31-Dec-2016	64 m 21 d
Manufacture Date: 31-Dec-2010										
262003 AFT RIGHT	ENGINE FIRE EXTINGUISHER CARTRIDGE SEE			M13083-5 12110	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		72		31-Dec-2016	64 m 21 d
Manufacture Date: 31-Dec-2010										
262003 FORWARD LEFT	ENGINE FIRE EXTINGUISHER CARTRIDGE CRQ			AE13083-5 808	MTH 27-Apr-2009 HRS 4854		120	0	30-Apr-2013	20 m 20 d
262003 FORWARD RIGHT	ENGINE FIRE EXTINGUISHER CARTRIDGE CRQ			AE13083-5 808	MTH 27-Apr-2009 HRS 4854		120	0	30-Apr-2013	20 m 20 d
271001	AILERON TRIM TAB ACTUATOR *CF			5565450-51 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
272001	RUDDER TRIM TAB ACTUATOR *CF			5565450-53 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
273002	ELEVATOR TRIM ELECTRICAL ACTUATOR *CF			5115231-19 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
273003	ELEVATOR TRIM TAB ACTUATOR *CF			5565450-54 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
275001 LEFT	FLAP MOTOR 9910055-4	LTN		FS30-5 348	MTH 04-Mar-1991 HRS 2965		O/C	0		
275001 RIGHT	FLAP MOTOR 9910055-4	MYF		FS30-5 502	MTH 02-Jul-2007 HRS 4741		O/C	0		
275002 LEFT	FLAP GEARBOX	DRO		5565175-38 412907	MTH 01-Feb-2002 HRS 4245		3000	0	7245	2264
275002 RIGHT	FLAP GEARBOX	DRO		5565175-38 412906	MTH 01-Feb-2002 HRS 4245		3000	0	7245	2264
276001 LEFT	SPEED BRAKE ACTUATOR GJT			5527230-1 S110542	MTH 16-Feb-2000		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR GJT			5527230-1 S110653	MTH 16-Feb-2000		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
281002 LEFT AFT	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
281002 LEFT FORWARD	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
281002 LEFT MID	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
281002 RIGHT AFT	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
281002 RIGHT FORWARD	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
281002 RIGHT MID	FUEL DRAIN VALVE 9912083-1	MAL		6904-079 SN-UNKNOWN	MTH 26-Feb-1985 HRS 1228		O/C	0		
282001 LEFT	FUEL BOOST PUMP 9912017-2	*CF		1C7-12 2F28	MTH 12-Sep-1980		O/C			
282001 RIGHT	FUEL BOOST PUMP 9912017-2	*CF		1C7-12 2F29	MTH 12-Sep-1980		O/C			
282005 LEFT	FUEL CROSSFEED VALVE 9912014-1	SEE		230125-3 373	MTH 29-Jun-2009 HRS 4867		O/C	0		
282009 LEFT	FILTER ELEMENT-FUEL -- SEE	SEE		AN6235-3A NSN	MTH 16-Dec-2010 HRS 4935.5 LDG 5324		12	0	31-Dec-2011	4 m 21 d
282009 RIGHT	FILTER ELEMENT-FUEL -- SEE	SEE		AN6235-3A NSN	MTH 16-Dec-2010 HRS 4935.5 LDG 5324		12	0	31-Dec-2011	4 m 21 d
284001 LEFT	LOW FUEL LEVEL SWITCH *CF	*CF		L15H-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
284001 RIGHT	LOW FUEL LEVEL SWITCH *CF	*CF		L15H-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 13164P	MTH 12-Sep-1980		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 702293	MTH 12-Sep-1980		O/C			
284003 LEFT WING	SECTION (61.00) FUEL QUANTITY PROBE 9912019-16	*CF		3266005-0401 404111	MTH 12-Sep-1980		O/C			
284003 RIGHT WING	SECTION (61.00) FUEL QUANTITY PROBE 9912019-8	*CF		391046-218 1526D	MTH 12-Sep-1980		O/C			
284004 LEFT WING	SECTION (129.00) FUEL QUANTITY PROBE 9912019-7	*CF		391046-219 1718D	MTH 12-Sep-1980		O/C			
284004 RIGHT WING	SECTION (129.00) FUEL QUANTITY PROBE 9912019-7	*CF		391046-219 1706D	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284005 LEFT WING	SECTION (171.50) FUEL QUANTITY PROBE 9912019-14	*CF		3266005-0201 609216	MTH 12-Sep-1980		O/C			
284005 RIGHT WING	SECTION (171.50) FUEL QUANTITY PROBE 9912019-14	*CF		3266005-0201 609239	MTH 12-Sep-1980		O/C			
284006 LEFT WING	SECTION (211.00) FUEL QUANTITY PROBE 9912019-5	*CF		391046-221 1702D	MTH 12-Sep-1980		O/C			
284006 RIGHT WING	SECTION (211.00) FUEL QUANTITY PROBE 9912019-5	*CF		391046-221 1365D	MTH 12-Sep-1980		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-7	MYF		VSDL-OC203C 41	MTH 25-Feb-2008 HRS 4792		O/C	0		
291001	HYDRAULIC RESERVOIR 9912052-2	*CF		7140-150-2 912	MTH 12-Sep-1980		O/C			
291002 NO. 1 ENGINE	HYDRAULIC PUMP 9912062-1	*CF		67U100 B0-401	MTH 12-Sep-1980		O/C			
291002 NO. 2 ENGINE	HYDRAULIC PUMP 9912062-1	*CF		67U100 B0-352	MTH 12-Sep-1980		O/C			
291004 RIGHT	SUCTION SHUTOFF VALVE 9912062-1	*CF		149145 1538	MTH 12-Sep-1980		O/C			
291010	HYDRAULIC PRESSURE SWITCH MYF			1106P59 4533	MTH 16-Jan-2007 HRS 4712		O/C	0		
291014	HYDRAULIC SAFETY CHECK VALVE *CF			262A4TB SN-UNKNOWN	MTH 12-Sep-1980		O/C			
301001 LEFT WING	DE-ICE BOOT SEE			SMR5059-07 0004	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
301002 RIGHT WING	DE-ICE BOOT MYF			25S-7D5059-08 MYGGG90	MTH 14-Mar-2006 HRS 4669		O/C	0		
301003 LEFT	HORIZONTAL STABILIZER DE-ICE BOOT LTN			25S-7D5059-03 SN-UNKNOWN	MTH 04-Mar-1991 HRS 2965		O/C	0		
301003 RIGHT	HORIZONTAL STABILIZER DE-ICE BOOT LTN			25S-7D5059-03 SN-UNKNOWN	MTH 04-Mar-1991 HRS 2965		O/C	0		
301004 VERTICAL STABILIZER	DE-ICE BOOT LTN			25S-7D5059-05 SN-UNKNOWN	MTH 04-Mar-1991 HRS 2965		O/C	0		
301005 LEFT	ANTI-ICE ELEMENT 9912081-7	*CF		2E1469-1 254	MTH 12-Sep-1980		O/C			
301006 RIGHT	ANTI-ICE ELEMENT 9912081-8	*CF		2E1469-8 166	MTH 12-Sep-1980		O/C			
301007 AFT	DE-ICE PRESSURE SWITCH CNO			1106P55 SN-UNKNOWN	MTH 21-Apr-2005 HRS 4591		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301007 FORWARD	DE-ICE PRESSURE SWITCH	*CF		1106P55 699	MTH 12-Sep-1980		O/C			
301008 LEFT WING	DE-ICE VALVE	*CF		3D2353-06 N2888	MTH 12-Sep-1980		O/C			
301008 RIGHT WING	DE-ICE VALVE	*CF		3D2353-06 N2958	MTH 12-Sep-1980		O/C			
301008	STABILIZER AND FIN DE-ICE VALVE	*CF		3D2353-06 N2315	MTH 12-Sep-1980		O/C			
301009	AIRFOIL DE-ICE TIMER	*CF		76-1A SN-UNKNOWN	MTH 12-Sep-1980		O/C			
301010 LEFT WING	ANTI-ICE ASSEMBLY	LTN		5528007-207 SN-UNKNOWN	MTH 04-Mar-1991 HRS 2965		O/C	0		
301010 RIGHT WING	ANTI-ICE ASSEMBLY	*CF		5528007-208 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
302001	ALCOHOL PUMP	*CF		476411 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
302002	BLEED AIR CHECK VALVE	*CF		85300 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
302003 LEFT	ANTI-ICE SOLENOID VALVE 9912086-1	*CF		226395 0171	MTH 12-Sep-1980		O/C			
302003 RIGHT	ANTI-ICE SOLENOID VALVE 9912086-7	DRO		67410-1 2704ABCDEG	MTH 28-May-2002 HRS 4307		O/C	0		
303001 LEFT	PITOT TUBE	GJT		PH502 SN-UNKNOWN	MTH 27-Feb-2001 HRS 4062		O/C	0		
303001 RIGHT	PITOT TUBE	GJT		PH502 SN-UNKNOWN	MTH 27-Feb-2001 HRS 4062		O/C	0		
303002 LEFT LOWER	PILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
303002 RIGHT LOWER	COPILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
303003 LEFT UPPER	COPILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
303003 RIGHT UPPER	PILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
304001	HOT AIR TEMPERATURE MONITOR ZRH			1169-1 1386	MTH 09-Jun-1986 HRS 1713		O/C	0		
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 4F0170	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
304006	TEMPERATURE CONTROLLER 9912085-2	ZRH		27231272 6AA33	MTH 09-Jun-1986 HRS 1713		O/C	0		
304007 LEFT	TEMPERATURE SENSOR 9912085-3	*CF		27221274 2E0252	MTH 12-Sep-1980		O/C			
304007 RIGHT	TEMPERATURE SENSOR 9912085-3	*CF		27221274 0E0169	MTH 12-Sep-1980		O/C			
304008	PRESSURE SWITCH	*CF		1115P25 502	MTH 12-Sep-1980		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR SOLENOID VALVE 9912086-2	*CF		226395-1 231	MTH 12-Sep-1980		O/C			
312001 AFT	DIGITAL CLOCK	*CF		811B 11861	MTH 12-Sep-1980		O/C			
312002	CLOCK BATTERY	SEE		811-BATT-1 NSN	MTH 16-Jun-2010 HRS 4921 LDG 5297		36 0	0 0	30-Jun-2013	22 m 20 d
313001	FLIGHT HOUR METER 85326	DRO		C664503-0103 SN-UNKNOWN	MTH 26-Oct-2000 HRS 3995		O/C	0		
321001 LEFT MAIN LANDING GEAR	ASSEMBLY	*CF		5541000-11 557	MTH 12-Sep-1980		O/C			
321002 RIGHT MAIN LANDING GEAR	ASSEMBLY	*CF		5541000-12 552	MTH 12-Sep-1980		O/C			
322001 NOSE GEAR	ASSEMBLY	*CF		5542000-7 718	MTH 12-Sep-1980 LDG 0		41000	0	41000	35609
322002 NOSE LANDING GEAR	SHIMMY DAMPER	MAL		5543001-3 444	MTH 03-Oct-1985 HRS 1488 LDG 1584		O/C	0		
322004 NOSE LANDING GEAR	FORK	*CF		5542300-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
322005 NOSE LANDING GEAR	ACTUATOR FITTING	*CF		5511169-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
322006 LEFT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		5513056-5 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		22500	0	22500	17109
322006 RIGHT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		5513056-6 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		22500	0	22500	17109
322007 NOSE LANDING GEAR	TRUNION	*CF		5542301-5 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		22500	0	22500	17109
322008 LEFT MAIN GEAR	TRUNNION ATTACH PIN	*CF		5541205-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322008 RIGHT MAIN GEAR	TRUNNION ATTACH PIN	*CF		5541205-4 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322009 LEFT MAIN GEAR	ACTUATOR PIN	*CF		6527213-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322009 RIGHT MAIN GEAR	ACTUATOR PIN	*CF		6527213-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322010 LEFT MAIN GEAR	ACTUATOR ATTACH STUD	*CF		6541204-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322010 RIGHT MAIN GEAR	ACTUATOR ATTACH STUD	*CF		6541204-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322011 LEFT MAIN GEAR	TRUNNION	*CF		5541306-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322011 RIGHT MAIN GEAR	TRUNNION	*CF		5541306-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322012 LEFT MAIN GEAR	AXLE	*CF		6541200-1 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322012 RIGHT MAIN GEAR	AXLE	*CF		6541200-1 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322013 LEFT MAIN GEAR	UPPER PISTON BEARING	*CF		5541310-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322013 RIGHT MAIN GEAR	UPPER PISTON BEARING	*CF		5541310-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322014 LEFT MAIN GEAR	UPPER TORQUE LINK	*CF		5541304-9 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	28600	2728	28600	23209
322014 RIGHT MAIN GEAR	UPPER TORQUE LINK	*CF		5541304-10 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	28600	2728	28600	23209
322015 LEFT MAIN GEAR	LOWER TORQUE LINK	*CF		5541304-11 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	28600	2728	28600	23209
322015 RIGHT MAIN GEAR <i>322015L : RL</i>	LOWER TORQUE LINK	*CF		5541304-6 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	41600	2728	41600	36209
322016 LEFT MAIN GEAR	TORQUE LINK SHAFT	*CF		6541212-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322016 RIGHT MAIN GEAR	TORQUE LINK SHAFT	*CF		6541212-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322017 LEFT MAIN GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	41600	2761	41600	36209
322017 RIGHT MAIN GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	41600	2761	41600	36209
322018 LEFT MAIN GEAR	TORQUE LINK NUT	*CF		MS17825-8 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322018 RIGHT MAIN GEAR	TORQUE LINK NUT	*CF		MS17825-8 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	28600	2761	28600	23209
322019 NOSE GEAR	PISTON ASSEMBLY	*CF		5542105-2 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
322020 NOSE GEAR	CYLINDER BRAZE ASSEMBLY	*CF		5542100-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	22500	2761	22500	17109
322021 NOSE GEAR	AXLE SPACER	*CF		5542223-1 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	22500	2761	22500	17109
322022 NOSE GEAR	TORQUE LINK SHAFT	*CF		5542208-3 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2761	22500	2761	22500	17109
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912053-17	*CF		1523100-1 12	MTH 12-Sep-1980 LDG 0		37500	0	37500	32109
323002 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912053-18	*CF		1523100-2 9	MTH 12-Sep-1980 LDG 0		37500	0	37500	32109
323003 NOSE LANDING GEAR	ACTUATOR ASSEMBLY 9912063-13	*CF		2-7406-1 DA239	MTH 12-Sep-1980 LDG 0		32600	0	32600	27209
323004 LEFT MAIN LANDING GEAR	UPLOCK ACTUATOR	SEE		5527504-2 CE359	MTH 28-Jan-2011 HRS 4939.8 LDG 5328		O/C			
323004 NOSE LANDING GEAR	UPLOCK ACTUATOR	*CF		5527504-2 2128	MTH 12-Sep-1980		O/C			
323004 RIGHT MAIN LANDING GEAR	UPLOCK ACTUATOR	*CF		5527504-2 2122	MTH 12-Sep-1980		O/C			
323006	EMERGENCY GEAR AIR BOTTLE 9912103-1	MYF		23111321 7031632	MTH 11-Apr-2008 HRS 4796		180	129	31-Jul-2012	11 m 21 d
323007	LANDING GEAR CONTROL VALVE	*CF		2710969 0802	MTH 12-Sep-1980		O/C			
323008 RIGHT MAIN LANDING GEAR	CYLINDER ASSEMBLY	*CF		5541109-6 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	16100	2728	16100	10709
323014 LEFT MAIN LANDING GEAR	CYLINDER ASSEMBLY	*CF		5541109-5 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0	2728	16100	2728	16100	10709
323018 LEFT MAIN LANDING GEAR	PISTON WELD ASSEMBLY	*CF		5541108-5 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		15000	0	15000	9609
323018 RIGHT MAIN LANDING GEAR	PISTON WELD ASSEMBLY	*CF		5541108-6 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		15000	0	15000	9609
323019	EMERGENCY AIR BOTTLE GAGE	*CF		2341128 SN-UNKNOWN	MTH 12-Sep-1980		O/C	0		
324001 LEFT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912222-11	DRO		3-1490-1 1147	MTH 06-Aug-2002 HRS 4355 LDG 4620		O/C			1360

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324001 RIGHT MAIN LANDING GEAR	WHEEL ASSEMBLY 9912222-11	DRO		3-1490-1 1174	MTH 09-Nov-2001 HRS 4202 LDG 4385		O/C			1125
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY	DRO		9544207 SN-UNKNOWN	MTH 17-Oct-2001 HRS 4181 LDG 4359		O/C			4359
324003 LEFT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912246-28	SEE		2-1530-4 1563	MTH 16-Jun-2010 HRS 4921 LDG 5297		749	0		6046
<i>324003T : LTR</i>										
324004 RIGHT MAIN LANDING GEAR	BRAKE ASSEMBLY 9912246-28	SEE		2-1530-4 0398	MTH 16-Jun-2010 HRS 4921 LDG 5297		749	0		6046
<i>324004T : RTR</i>										
324005 LEFT MAIN GEAR	TIRE	SEE		220K08-3 00192574	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0		0
<i>324005T : LTR</i>										
324005 RIGHT MAIN GEAR	TIRE	MYF		220K08-3 61780680	MTH 02-Jul-2007 HRS 4741 LDG 5080		O/C			0
<i>324005T : RTR</i>										
324006 NOSE LANDING GEAR	TIRE	MYF		184F10-2 62340706	MTH 02-Jul-2007 HRS 4741 LDG 5080		O/C			0
324011 COPILOT INBOARD	BRAKE MASTER CYLINDER 9912050-9	*CF		12A085-9 1456	MTH 12-Sep-1980		O/C			
324011 PILOT OUTBOARD	BRAKE MASTER CYLINDER 9912050-9	*CF		12A085-9 1290	MTH 12-Sep-1980		O/C			
324012 COPILOT OUTBOARD	BRAKE MASTER CYLINDER 9912050-10	PBI		12A085-10 1025	MTH 13-Apr-1981 HRS 117 LDG 155		O/C			0
324012 PILOT INBOARD	BRAKE MASTER CYLINDER 9912050-10	*CF		12A085-10 1501	MTH 12-Sep-1980		O/C			
324013	PARKING BRAKE VALVE	*CF		AS20800-1 579	MTH 12-Sep-1980		O/C			0
324014	EMERGENCY BRAKE VALVE 9912105-1	*CF		53640 234A	MTH 12-Sep-1980		O/C			
326001	GEAR WARNING HORN 9910080-1	*CF		A2948 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
326002 RIGHT MAIN GEAR	UP AND LOCKED SWITCH	MYF		5508012-18 NSN	MTH 19-Aug-2007 HRS 4753 LDG 5092		O/C			0
331001	ANNUNCIATOR PANEL 9912167-11	*CF		D3474-11 2	MTH 12-Sep-1980		O/C			
331011	ELECTRICAL PANEL LIGHT INVERTER	*CF		EM2044 703	MTH 12-Sep-1980		O/C			
331012	MASTER WARNING SWITCH	*CF		1941-4 SN-UNKNOWN	MTH 12-Sep-1980		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
334002	VERTICAL FIN ANTI-COLLISION LIGHT DRO			40-0100-1 3560	MTH 12-Feb-2004 HRS 4475		O/C	0		
334003 LEFT	STROBE POWER SUPPLY 9910368-2	*CF		60-2799-1 6092	MTH 12-Sep-1980		O/C			
334003 RIGHT	STROBE POWER SUPPLY 9910368-2	MYF		60-2799-1 14569	MTH 16-May-2006 HRS 4670		O/C	0		
335001	EMERGENCY LIGHTING BATTERY *CF			24621-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C	0		
341001 LEFT	AIRSPEED INDICATOR	MYF		AW2837AC03 W978H	MTH 31-Jul-2007 HRS 4741		O/C	0		
341001 RIGHT	AIRSPEED INDICATOR	SEE		C661063-0103 46	MTH 22-Feb-2010 HRS 4900		O/C	46		
341002 COPILOT	ALTIMETER 10450-11139	MYF		C661072-0102 1045011139	MTH 25-Feb-2003 HRS 4396		O/C	475		
341002 PILOT	ALTIMETER BA-141	MYF		4016341-905 81032041	MTH 02-Feb-1999 HRS 3651		O/C	3601		
341004	OUTSIDE AIR TEMPERATURE GAUGE 162BL507D	*CF		C668510-0401 764	MTH 12-Sep-1980		O/C			
341005	OVERSPEED WARNING SWITCH 9912076-9	ICT		DRA45C-39 563	MTH 29-Sep-1982 HRS 353		O/C	0		
341006	OVERSPEED WARNING HORN CAE			SC628P SN-UNKNOWN	MTH 08-Oct-1999 HRS 3715		O/C	0		
341010	ANGLE OF ATTACK INDICATOR *CF			SLZ9686-1 PC1481	MTH 12-Sep-1980		O/C			
341012	ANGLE OF ATTACK POTENTIOMETER *CF			MOD202-5K SN-UNKNOWN	MTH 12-Sep-1980		O/C			
341013	ANGLE OF ATTACK TRANSMITTER ZRH			SLZ9386 GU0921C	MTH 21-Apr-1989 HRS 2435		O/C	0		
341014	ANGLE OF ATTACK INDEXER *CF			SLZ9374 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
341020	VERTICAL NAVIGATIONAL CONTROLLER/ VN-212	DRO		4020571-904 81051283	MTH 02-Jul-2002 HRS 4334		O/C	4573		
341021	RADIO ALTIMETER INDICATOR RA-315	ICT		7000839-903 052296	MTH 14-Sep-1982 HRS 353		O/C	0		
342001	MAGNETIC COMPASS	SEE		C2400WOR JL00109	MTH 22-Feb-2010 HRS 4900		O/C	0		
342002 RIGHT	TURN & BANK INDICATOR	DMO		C661004-0101 860881	MTH 25-Sep-1996 HRS 3468		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342002	TURN AND BANK INDICATOR DMO			C661004-0101 822592	MTH 25-Sep-1996 HRS 3468		O/C	0		
342003 RIGHT	HORIZON GYRO 1U149-002-2	DRO		C661056-0202 A259	MTH 30-Sep-2003 HRS 4460		O/C	0		
342021 LEFT	VERTICAL SPEED INDICATOR MAL			C661006-0101 W12336H	MTH 28-Mar-1985 HRS 1255		O/C	0		
342021 RIGHT	VERTICAL SPEED INDICATOR MAL			C661006-0101 W11963H	MTH 28-Mar-1985 HRS 1255		O/C	0		
342041 NO. 1	FLIGHT DIRECTOR COMPUTER	ZRH		4018369-905 91967	MTH 27-Nov-1985 HRS 1553		O/C	891		
342042 LEFT	AP/FD MODE SELECTOR	*CF		4020570-901 040797	MTH 12-Sep-1980		O/C			
342043 NO. 1	VERTICAL GYRO VG-14A	GJT		7000622-901 81032731	MTH 04-May-2001 HRS 4087		O/C	0		
342047 LEFT	ADI --	ZRH		4002531-901 79080555	MTH 21-Apr-1989 HRS 2435		O/C	0		
342048 NO. 1	AIR DATA COMPUTER AZ-241	CRQ		4013241-901 6070250	MTH 15-Apr-2009 HRS 4854		O/C	0		
342049 LEFT	DIR GYRO SYN COMPASS C-14D	MYF		4020577-3 83103114	MTH 30-Jul-2004		O/C			
342049 RIGHT	DIR GYRO SYN COMPASS	GJT		4020577-3 98016357	MTH 07-Jun-2000 HRS 3879		O/C	834		
342050 NO. 1	FLUX VALVE FX-220	KBI		2594484 86023820	MTH 09-Feb-1998 HRS 3499		O/C	0		
342050 NO. 2	FLUX VALVE FX-220	*CF		2594484 012641	MTH 12-Sep-1980		O/C			
342052	DUAL REMOTE COMPENSATOR CS-412	*CF		2593379-1 074062	MTH 12-Sep-1980		O/C			
342054 LEFT	HSI --	GJT		2592920-901 79043153	MTH 04-May-2001 HRS 4087		O/C	0		
342054 RIGHT	HSI --	*CF		2592920-901 083348	MTH 12-Sep-1980		O/C			
344018	WEATHER RADAR INDICATOR IN-2707A	*CF		4001295-2704 1435	MTH 12-Sep-1980		O/C			
344020	RADAR ANTENNA -- DA-1230A	GJT		4000504-0301 2974	MTH 05-Jan-2000 HRS 3802		O/C	0		
344021 NO. 1	RADIO MAGNETIC INDICATOR 332C-10	*CF		622-0555-008 10767	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
344021 NO. 2	RADIO MAGNETIC INDICATOR 332C-10	*CF		622-0555-008 10748	MTH 12-Sep-1980		O/C			
344022	RADIO ALTIMETER TRANSCEIVER RT-220	*CF		4004437-901 103017	MTH 12-Sep-1980		O/C			
344023 AFT	RADIO ALTITUDE ANTENNA AT-224	*CF		4010504 011178	MTH 12-Sep-1980		O/C			
344023 FORWARD	RADIO ALTITUDE ANTENNA AT-224	*CF		4010504 011168	MTH 12-Sep-1980		O/C			
345004 NO. 1	ATC TRANSPONDER ANTENNA *CF			DMN150-2 15537	MTH 12-Sep-1980		O/C			
345004 NO. 2	ATC TRANSPONDER ANTENNA *CF			DMN150-2 15554	MTH 12-Sep-1980		O/C			
345007 NO. 1	DME ANTENNA *CF			DMNI50-2 15551	MTH 12-Sep-1980		O/C			
345008 NO. 1	COURSE DEVIATION INDICATOR *CF			520850 861	MTH 12-Sep-1980		O/C			
345010	NAV ANTENNA KIT *CF			DMN4-17-1B 13992	MTH 12-Sep-1980		O/C			
345011 NO. 1	ADF RECEIVER ADF-60A	ICT		622-2362-001 11938	MTH 29-Sep-1982 HRS 353		O/C	0		
345011 NO. 2	ADF RECEIVER ADF-60A	*CF		622-2362-001 5524	MTH 12-Sep-1980		O/C			
345012 NO. 1	ADF CONTROL *CF			156 1450	MTH 12-Sep-1980		O/C			
345012 NO. 2	ADF CONTROL ICT			156 1893B	MTH 29-Sep-1982 HRS 353		O/C	0		
345014 NO. 1	ADF LOOP ANTENNA APA-80	LIM		622-2363-001 6814	MTH 23-Jul-1993 HRS 3367		O/C	0		
345014 NO. 2	ADF LOOP ANTENNA APA-80	LBG		622-2363-001 5720	MTH 02-Sep-1986 HRS 1800		O/C	0		
345017	MARKER BEACON ANTENNA *CF			16D00400-2 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
345018	GLIDESLOPE ANTENNA *CF			RGS1048 7194	MTH 12-Sep-1980		O/C			
345021	RNAV DIST CONVERTER *CF			4000651-0601 1284	MTH 12-Sep-1980		O/C			
345032 BOTTOM	NO. 2 NAVIGATION RECEIVER *CF			622-0876-001 13582	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345032 TOP	NO. 1 NAVIGATION RECEIVER VIR-30	PBI		622-0876-001 9976	MTH 13-Apr-1981 HRS 117		O/C	22		
345034 NO. 1	ATC TRANSPONDER TDR-90	CRQ		622-1270-001 8486	MTH 15-Apr-2009 HRS 4854		O/C	4854		
345034 NO. 2	ATC TRANSPONDER TDR-90	CRQ		622-1270-001 9178	MTH 15-Apr-2009 HRS 4854		O/C	4854		
345035 NO. 2	DME INDICATOR 339F-12A	*CF		622-2012-201 2139	MTH 12-Sep-1980		O/C			
345036 NO. 2	DME INTERROGATOR	LBG		622-1233-001 8403	MTH 10-Dec-1986 HRS 1849		O/C	0		
345118	GPS ANTENNA	GJT		071-01553-0200 21639	MTH 14-Feb-2000 HRS 3828		O/C	0		
345132	GPS RECEIVER/ SENSOR	DRO		066-04031-2422 81590	MTH 30-May-2003 HRS 4413		O/C	0		
345149	GPS INTERFACE ANNUNCIATOR CONTROL	GJT		MD41-328 11794	MTH 14-Feb-2000 HRS 3828		O/C	0		
346035	HSI ADAPTER -- KA-90	GJT		071-01508-0202 3136	MTH 14-Feb-2000 HRS 3828		O/C	0		
346036	AIR DATA UNIT --	GJT		9004-00348111039 104280	MTH 14-Feb-2000 HRS 3828		O/C	0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 W9778E	MTH 12-Sep-1980		O/C	0		
351004 COPILOT	OXYGEN MASK 9912057-3	*CF		ZMR140 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
351004 PILOT	OXYGEN MASK			174045-15 07657	MTH 24-Oct-2000 HRS 3992		O/C	0		
351005	OXYGEN REGULATOR 9912057-2	*CF		ZR807 3240	MTH 12-Sep-1980		O/C	0		
351006	OXYGEN CYLINDER 9912057-2	DRO		ZC371 4228	MTH 20-May-2004 HRS 4506		288	0	31-May-2028	201 m 21 d
361001	DOOR SEAL CONTROL VALVE *CF			MJV3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
361002	INSTRUMENT REGULATOR 9912043-1	LIM		38E85-4C RE661	MTH 23-Jul-1993 HRS 3367		O/C	0		
361003	DEICE BOOT REGULATOR 9912043-2	*CF		38E85-5C 772U	MTH 12-Sep-1980		O/C			
361004	PNEUMATIC (BLEED AIR) PRESSURE REGULATOR *CF			2102702-5 SN-UNKNOWN	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361005 RIGHT	GYRO PRESSURE GAUGE	*CF		C668515-0101 W5600G	MTH 12-Sep-1980		O/C			
361006	FORWARD INSTRUMENT BLEED AIR PRESSURE REGULATOR	*CF		3H64-4 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
521001 CABIN	DOOR SEAL	MYF		5511230-60 N/A	MTH 11-Jun-2008 HRS 4804		O/C	0		
526001 CABIN	DOOR STEP	*CF		6519009-20 326	MTH 12-Sep-1980		O/C			
561001 LEFT MAIN	WINDSHIELD 9912064-7			CES-507-017-0 82	MTH 08-Oct-1999 HRS 3715		O/C	0		
561002 RIGHT MAIN	WINDSHIELD 9912064-8	*CF		CES-507-018-0 H46324	MTH 12-Sep-1980		O/C			
561003	FOUL WEATHER WINDOW	CAE		5511275-201 SN-UNKNOWN	MTH 08-Oct-1999 HRS 3715		O/C	0		
561005 COPILOT INBOARD	WINDOW	*CF		5511285-6 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
561005 COPILOT OUTBOARD	WINDOW	DRO		PAS5511285-4 0157	MTH 24-Mar-2001 HRS 4079		O/C	0		
561005 PILOT INBOARD	WINDOW	CNO		PAS5511285-5 0222	MTH 21-Apr-2005 HRS 4591		O/C	0		
561005 PILOT OUTBOARD	WINDOW	*CF		5511285-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
562001 LEFT AFT	CABIN WINDOW	SEE		5591005-5 10714	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 LEFT CENTER AFT	CABIN WINDOW	SEE		5591005-5 10701	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 LEFT CENTER FORWARD	CABIN WINDOW	SEE		5591005-5 10705	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 LEFT FORWARD	CABIN MAIN DOOR WINDOW	SEE		5591005-5 10704	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 RIGHT AFT	CABIN WINDOW	SEE		5591005-5 10730	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 RIGHT CENTER AFT	CABIN WINDOW	SEE		5591005-5 10703	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 RIGHT CENTER FORWARD	CABIN WINDOW	SEE		5591005-5 10721	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	
562001 RIGHT FORWARD	CABIN EMERGENCY DOOR WINDOW	SEE		5591005-5 10731	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0	0	

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
572001 LEFT FORWARD	TRUNNION FITTING ASSEMBLY *CF			5522700-1 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		20000	0	20000	14609
572002 RIGHT FORWARD	TRUNNION FITTING ASSEMBLY *CF			5522700-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		20000	0	20000	14609
574001 LEFT AFT	TRUNNION FITTING ASSEMBLY *CF			5522710-1 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		41600	0	41600	36209
574002 RIGHT AFT	TRUNNION FITTING ASSEMBLY *CF			5522710-2 SN-UNKNOWN	MTH 12-Sep-1980 LDG 0		41600	0	41600	36209
574003 LEFT	SIDEBRACE FITTING ASSEMBLY *CF			5522720-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
574004 RIGHT	SIDEBRACE FITTING ASSEMBLY *CF			5522720-2 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
710002 LEFT ENGINE	BY-PASS NOZZLE ASSEMBLY *CF			5555030-18 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
710002 RIGHT ENGINE	BY-PASS NOZZLE ASSEMBLY *CF			5555030-18 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
712001 LEFT ENGINE AFT	ISOLATOR MOUNT 9912028-2	KBI		LM420SA6 SN-UNKNOWN	MTH 09-Feb-1998 HRS 3499		3500	0	6999	2018
712001 RIGHT ENGINE AFT	ISOLATOR MOUNT 9912028-2	KBI		LM420SA6 304	MTH 16-Feb-1996 HRS 3430		3500	0	6930	1949
712002 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912028-3	KBI		LM420SA5 538	MTH 09-Feb-1998 HRS 3499		3500	0	6999	2018
712002 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912028-3	KBI		LM420SA5 521	MTH 09-Feb-1998 HRS 3499		3500	0	6999	2018
712002 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912028-3	KBI		LM420SA5 662	MTH 16-Feb-1996 HRS 3430		3500	0	6930	1949
712002 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912028-3	KBI		LM420SA5 643	MTH 16-Feb-1996 HRS 3430		3500	0	6930	1949
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 3018700	EKB		JT15D-1A 77209	MTH 15-Sep-1999 HRS 3695		E/C	0		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 3018700	EKB		JT15D-1A 77210	MTH 10-Nov-1995 HRS 3430		E/C	0		
722001 E1	OIL PUMP	MYF		3029284 2708	MTH 10-Oct-2005 HRS 4621		O/C	0		
722001 E2	OIL PUMP	EKB		3030391 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
723001 E1	FAN	EKB		3018020 SN-UNKNOWN	MTH 15-Sep-1999 HRS 3695		O/C	121		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723001 E2	FAN	EKB		3018020 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
723010 E1	CENTRIFUGAL IMPELLER	EKB		3032145 1B449	MTH 15-Sep-1999 HRS 3695 LDG 3633		8400	3542	8491	3100
<i>724825 : E1**L</i>										
723010 E2	CENTRIFUGAL IMPELLER	EKB		3032145 1B446	MTH 10-Nov-1995 HRS 3430 LDG 3293		8400	3249	8444	3053
<i>724825 : E2**R</i>										
723030 E1	LOW PRESSURE COMPRESSOR HUB	EKB		3018018 1E627	MTH 15-Sep-1999 HRS 3695 LDG 3633		13750	3542	13841	8450
<i>722607 : E1**L</i>										
723030 E2	LOW PRESSURE COMPRESSOR HUB	EKB		3018018 1E648	MTH 10-Nov-1995 HRS 3430 LDG 3293		13750	3249	13794	8403
<i>722607 : E2**R</i>										
725010 E1	HIGH PRESSURE TURBINE ROTOR DISK	EKB		3023411 5E603	MTH 15-Sep-1999 HRS 3695 LDG 3633		14000	3542	14091	8700
<i>724706 : E1**L</i>										
725010 E2	HIGH PRESSURE TURBINE ROTOR DISK	EKB		3023411 PA1519	MTH 10-Nov-1995 HRS 3430 LDG 3293		14000	3249	14044	8653
<i>724706 : E2**R</i>										
725020 E1	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK	EKB		3022212 9L858	MTH 15-Sep-1999 HRS 3695 LDG 3633		14000	3542	14091	8700
<i>723705 : E1**L</i>										
725020 E2	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK	EKB		3022212 9D814	MTH 10-Nov-1995 HRS 3430 LDG 3293		14000	3249	14044	8653
<i>723705 : E2**R</i>										
725030 E1	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK	EKB		3021213 9D347	MTH 15-Sep-1999 HRS 3695 LDG 3633		14000	3542	14091	8700
<i>724006 : E1**L</i>										
725030 E2	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK	EKB		3036113 9D351	MTH 10-Nov-1995 HRS 3430 LDG 3293		14000	3249	14044	8653
<i>724006 : E2**R</i>										
725071 E1	COMBUSTION LINER	EKB		3029994 SN-UNKNOWN	MTH 15-Sep-1999 HRS 3695		O/C	121		
<i>724001 : E1**L</i>										
725071 E2	COMBUSTION LINER	EKB		3029994 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
<i>724001 : E2**R</i>										
731004 NO. 1 ENGINE	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		613-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
731004 NO. 2 ENGINE	LOW FUEL PRESSURE SWITCH 9912033-2	DRO		1103P0448 4719	MTH 28-May-2001 HRS 4099		O/C	0		
732002	ENGINE SYNCHRONIZER CONTROL *CF			213723 17368J	MTH 12-Sep-1980		O/C			
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 7788AE	MTH 12-Sep-1980		O/C			
733002	FUEL FLOW INDICATOR 9912147-17	SEE		VSDL-OC408D 162AC	MTH 16-Jun-2010 HRS 4921 LDG 5297		O/C	0		
733003 NO. 1 ENGINE	FUEL FLOWMETER 9912031-4	GJT		3268005-0101 707325	MTH 16-Feb-2000		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
733003 NO. 2 ENGINE	FUEL FLOWMETER 9912031-4	*CF		3268005-0101 911594	MTH 12-Sep-1980		O/C			
731010 E1 <i>731001 : E1**L</i>	FUEL PUMP 3023293	EKB		025493-402-04 439	MTH 15-Sep-1999 HRS 3695		O/C	121		
731010 E2 <i>731001 : E2**R</i>	FUEL PUMP 3026909	EKB		025493-401-05 2036	MTH 10-Nov-1995 HRS 3430		O/C	0		
731020 E1 <i>792002 : E1**L</i>	FUEL-OIL COOLER 3015303	EKB		UA530768-4 1907	MTH 15-Sep-1999 HRS 3695		O/C	121		
731020 E2 <i>792002 : E2**R</i>	FUEL-OIL COOLER 3015303	EKB		UA530768-4 1921	MTH 10-Nov-1995 HRS 3430		O/C	0		
731030 E1 <i>282010 : E1**L</i>	MOTIVE FLOW VALVE 3017930	EKB		2524995 A70273	MTH 15-Sep-1999 HRS 3695		O/C	121		
731030 E2 <i>282010 : E2**R</i>	MOTIVE FLOW VALVE 3017930	EKB		2524995 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
731040 E1 <i>731002 : E1**L</i>	FLOW DIVIDER VALVE 3024476	EKB		25607-2 2030	MTH 15-Sep-1999 HRS 3695		O/C	121		
731040 E2 <i>731002 : E2**R</i>	FLOW DIVIDER VALVE 3024476	EKB		25607-2 2036	MTH 10-Nov-1995 HRS 3430		O/C	0		
732010 E1 <i>732001 : E1**L</i>	FUEL CONTROL UNIT	EKB		3030251 A60245	MTH 15-Sep-1999 HRS 3695		O/C	105		
732010 E2 <i>732001 : E2**R</i>	FUEL CONTROL UNIT 3030251	KBI		3244763-2 A60386	MTH 15-Sep-1999 HRS 3695		O/C	0		
741010 E1 <i>741001 : E1**L</i>	IGNITION LOWER EXCITER 3016296	EKB		10-381550-2 88038904	MTH 15-Sep-1999 HRS 3695		O/C	121		
741010 E2 <i>741001 : E2**R</i>	IGNITION LOWER EXCITER 3016296	EKB		10-381550-2F 17814	MTH 10-Nov-1995 HRS 3430		O/C	0		
742010 E1 OUTBOARD <i>742001 : E1*LO</i>	IGNITER PLUG	MYF		FHE-246-4 N/A	MTH 11-Jun-2008 HRS 4804		O/C	0		
742010 E2 OUTBOARD <i>742001 : E2*RO</i>	IGNITER PLUG	MYF		FHE-246-4 N/A	MTH 11-Jun-2008 HRS 4804		O/C	0		
742020 E1 INBOARD <i>742001 : E1*LI</i>	IGNITER PLUG 3030595	MYF		FHE-246-4 N/A	MTH 11-Jun-2008 HRS 4804		O/C	0		
742020 E2 INBOARD <i>742001 : E2*RI</i>	IGNITER PLUG 3030595	MYF		FHE-246-4 N/A	MTH 11-Jun-2008 HRS 4804		O/C	0		
742030 E1 SHORT <i>742003 : E1**L</i>	IGNITER LEAD 3027940	EKB		10-395428-2 SN-UNKNOWN	MTH 15-Sep-1999 HRS 3695		O/C	121		
742030 E2 SHORT <i>742003 : E2**R</i>	IGNITER LEAD 3027940	EKB		10-395428-2 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742040 E1 LONG <i>742002 : E1**L</i>	IGNITER LEAD 3027939	EKB		10-395428-1 SN-UNKNOWN	MTH 15-Sep-1999 HRS 3695		O/C	121		
742040 E2 LONG <i>742002 : E2**R</i>	IGNITER LEAD 3027939	EKB		10-395428-1 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
750001 LEFT INBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-4	*CF		31A402 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
750001 LEFT OUTBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-4	*CF		31A402 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
750001 RIGHT INBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-2	*CF		31A402 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
750001 RIGHT OUTBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-2	*CF		31A402 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
750010 E1 <i>732004 : E1**L</i>	LOW PRESSURE COMPRESSOR ANTI-ICING 3029591	EKB		SOLENOID VALVE 3244758-1 C18078	MTH 15-Sep-1999 HRS 3695		O/C	121		
750010 E2 <i>732004 : E2**R</i>	LOW PRESSURE COMPRESSOR ANTI-ICING 3029591	EKB		SOLENOID VALVE 3244758-1 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		
751002 E1	BA SOL VALVE-STATORS -- MYF			KW15632 2080	MTH 13-Feb-2006 HRS 4658		O/C	0		
751002 E2	BA SOL VALVE-STATORS -- EKB			KW15632 2081	MTH 10-Nov-1995 HRS 3430		O/C	0		
761001	ENGINE CONTROL QUADRANT ASSEMBLY *CF			5565810-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
761002 NO. 1 ENGINE	MAIN THROTTLE CONTROL CABLE *CF			411D0315-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
761002 NO. 2 ENGINE	MAIN THROTTLE CONTROL CABLE *CF			411D0315-3 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
761003 NO. 1 ENGINE	NACELLE THROTTLE CONTROL CABLE *CF			7-42346-1 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
761004 NO. 2 ENGINE	NACELLE THROTTLE CONTROL CABLE *CF			7-42346-2 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
761005	DEPLOY INTERLOCK SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
771001 LEFT BOTTOM	N2 TACH GENERATOR *CF			22A623 2674	MTH 12-Sep-1980		O/C			
771001 LEFT TOP	N1 TACH GENERATOR *CF			22A623 1245	MTH 12-Sep-1980		O/C			
771001 RIGHT BOTTOM	N2 TACH GENERATOR *CF			22A623 1189	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
771001 RIGHT TOP	N1 TACH GENERATOR	*CF		22A623 1205	MTH 12-Sep-1980		O/C			
771002	N2 (TURBINE) INDICATOR 9912147-6	*CF		VSDL-OC410B 221B	MTH 12-Sep-1980		O/C			
771003	N1 (FAN) INDICATOR 9912147-20	MYF		VSDL-OC410L 50	MTH 08-May-2007 HRS 4733		O/C	0		
772001	ITT INDICATOR 9912147-4	DRO		VSDL-OC419A 40	MTH 20-May-2004 HRS 4506		O/C	0		
781001 NO. 1 ENGINE	EXHAUST NOZZLE CONE	*CF		5555025-18 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
781001 NO. 2 ENGINE	EXHAUST NOZZLE CONE	*CF		5555025-18 SN-UNKNOWN	MTH 12-Sep-1980		O/C			
783001 LEFT	THRUST REVERSER ASSEMBLY	*CF		202-0000-1 0317	MTH 12-Sep-1980		O/C			
783001 RIGHT	THRUST REVERSER ASSEMBLY	*CF		202-0000-3 0317	MTH 12-Sep-1980		O/C			
783002 LEFT	THRUST REVERSER CONTROL VALVE	*CF		AV14K1200 K928	MTH 12-Sep-1980		O/C			
783002 RIGHT	THRUST REVERSER CONTROL VALVE	*CF		AV14K1200 K932	MTH 12-Sep-1980		O/C			
783003 LEFT	THREE-WAY VALVE	*CF		13027-4 624	MTH 12-Sep-1980		O/C			
783003 RIGHT	THREE-WAY VALVE	*CF		13027-4 682	MTH 12-Sep-1980		O/C			
783005 LEFT UPPER	THRUST REVERSER DOOR	*CF		202-0001-1 0284	MTH 12-Sep-1980		O/C			
783005 RIGHT UPPER	THRUST REVERSER DOOR 9912110-1	*CF		202-0001-2 0284	MTH 12-Sep-1980		O/C			
783006 LEFT LOWER	THRUST REVERSER DOOR	*CF		202-0002-1 0284	MTH 12-Sep-1980		O/C			
783006 RIGHT LOWER	THRUST REVERSER DOOR	*CF		202-0002-2 0572	MTH 12-Sep-1980		O/C			
783007 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-1 0276	MTH 12-Sep-1980		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-1 0573	MTH 12-Sep-1980		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-3 0527	MTH 12-Sep-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1	*CF		202-0004-5 0528	MTH 12-Sep-1980		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT 9912110-1	*CF		202-0012-1 0571	MTH 12-Sep-1980		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT 9912110-1	*CF		202-0012-1 0570	MTH 12-Sep-1980		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		7U7555 1157	MTH 12-Sep-1980		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		7U7555 1155	MTH 12-Sep-1980		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		7U7555 1156	MTH 12-Sep-1980		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		7U7555 1158	MTH 12-Sep-1980		O/C			
793001	OIL TEMPERATURE INDICATOR 9912147-1	ZRH		VSDL-OC219A 8FCBA	MTH 21-Apr-1989 HRS 2435		O/C	0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER 9912147-1	*CF		MS28034-3 70477	MTH 12-Sep-1980		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER 9912147-1	*CF		MS28034-3 67191	MTH 12-Sep-1980		O/C			
793003	OIL PRESSURE INDICATOR 9912147-3	SEE		VSDL-OC204A 28AB	MTH 28-Jan-2011 HRS 4939.8 LDG 5328		O/C	4822.8		
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	SEE		123479 35623	MTH 28-Jan-2011 HRS 4939.8 LDG 5328		O/C	0 0		
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	*CF		123479 29766	MTH 12-Sep-1980		O/C			
792003 E1	OIL FILTER	MYF		3036376 N/A	MTH 16-May-2006 HRS 4670		O/C	0		
792003 E2	OIL FILTER	MYF		3036376 N/A	MTH 16-May-2006 HRS 4670		O/C	0		
832001 E1	MAIN GEARBOX ASSEMBLY	EKB		3018390 SN-UNKNOWN	MTH 15-Sep-1999 HRS 3695		O/C	121		
832001 E2	MAIN GEARBOX ASSEMBLY	EKB		3018390 SN-UNKNOWN	MTH 10-Nov-1995 HRS 3430		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-11-03 <i>11SB-3</i>	PLACARD INSTALLATION - AFT TOILET SEAT	PBI		MANDATORY	MTH 13-Apr-1981 HRS 117		A/R			Complete
SL 500-11-02 <i>11SL-2</i>	PLACARDS AND MARKINGS - DATA PLATE RELOCATION			OPTIONAL	MTH		A/R			
SL 500-20-02 R27	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
SB 500-21-08 <i>21SB-8</i>	SUPPLEMENTAL FLIGHT COMPARTMENT VENTILATION SYSTEM INSTALLATION			SUPERSEDED	MTH		A/R			
SB 500-21-15 <i>21SB-15</i>	FREON AIR CONDITIONING SYSTEM INSTALLATION			SUPERSEDED	MTH		A/R			
SB 500-21-16 <i>21SB-16</i>	AIRCONDITIONING - COCKPIT AIR DISTRIBUTION - ADD SUPPLEMENTARY AIR OUTLETS ON SIDE CONSOLES			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-19 <i>21SB-19</i>	AIR CONDITIONING - NOSE GEAR DOORS MODIFICATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-20 <i>21SB-20</i>	CABIN VENTILATION MOTOR REPLACEMENT			SUPERSEDED	MTH		A/R			
SB 500-21-21 <i>21SB-21</i>	OUTFLOW VALVE REPLACEMENT	KBI			MTH 10-Oct-1995 HRS 3410		A/R			Complete
SB 500-21-22 <i>21SB-22</i>	AIR CONDITIONING - ALTERNATE FLOW CONTROL VALVE INSTALLATION	DRO		OPTIONAL	MTH 28-Sep-2001 HRS 4156		A/R			Complete
SB 500-21-23 <i>21SB-23</i>	ADDITIONAL OUTFLOW VALVE REPLACEMENTS	KBI		MANDATORY	MTH 10-May-1995 HRS 3401		-			Complete
SB 500-21-24 <i>21SB-24</i>	AIR CONDITIONING - CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT	DRO		DISCRETIONARY	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-25	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL			A/R			
SL 500-21-11 <i>21SL-11</i>	INSPECTION/REPLACEMENT OF OUTFLOW/SAFETY VALVE POPPETS	PBI		MANDATORY	MTH 05-Nov-1980 HRS 42		A/R			Complete
SL 500-21-12 <i>21SL-12</i>	DEACTIVATION OF COOLING BLOWER THERMAL SWITCHES			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-21-15 <i>21SL-15</i>	ENGINE BLEED AIR CHECK VALVES			OPTIONAL	MTH		A/R			
SL 500-21-20 <i>21SL-20</i>	AIR CONDITIONING - COMPRESSOR DRIVE MOTOR BRUSH INSPECTION/REPLACEMENT (FORT WORTH AIRWORKS INC. - ZEPHYR AIR CONDITIONING)	UBI		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-22-07 <i>22SB-7</i>	AUTO FLIGHT - SINGLE AND DUAL ACCELEROMETER INSTALLATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-22-09 22SB-9	AUTO FLIGHT - FLIGHT DIRECTOR COMPUTER VERTICAL SPEED HOLD WIRING MODIFICATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-23-10 23SB-10	COMMUNICATION - FLITEFONE III INSTALLATION			SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-23-15 23SB-15	STATIC DISCHARGE IMPROVEMENT			SUPERSEDED	MTH		A/R			
SB 500-23-16 23SB-16	COMMUNICATIONS - STATIC WICK REPLACEMENT			*CF OPTIONAL	MTH		A/R			
SB 500-23-17 R1 23SB-17 : REV1	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		A/R			
SL 500-23-11 23SL-11	AVTECH AUDIO AMP - INSTALLATION OF INCREASED VOLTAGE CAPACITORS			SUPERSEDED	MTH		A/R			
SL 500-23-14 23SL-14	COMMUNICATION - 66 TRA MICROPHONE CORD REPLACEMENT PROGRAM	UBI		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-23-15 23SL-15	COMMUNICATION - STATIC DISCHARGE WICK MODIFICATION			OPTIONAL	MTH		A/R			
SB 500-24-05 24SB-5	ELECTRICAL - BATTERY TEMPERATURE MONITOR GAUGE SYSTEM			SUPERSEDED	MTH	15-Aug-1971	A/R			Complete
SB 500-24-12 24SB-12	BATTERY AND EXTERNAL POWER BOX RECEPTACLE GROUND IMPROVEMENT	HOU		SUPERSEDED	MTH HRS	21-Dec-1981 266	A/R			Complete
SB 500-24-13 24SB-13	300 VA INVERTER WATER SHIELD INSTALLATION	ZRH		OPTIONAL	MTH HRS	20-Jan-1983 464	A/R			Complete
SB 500-24-16 R1 24SB-16 : REV1	ELECTRICAL POWER - CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT			OPTIONAL	MTH		A/R			
SB 500-24-17 R2 24SB-17 : REV2	GENERATOR CONTROL UNIT START CIRCUIT MODIFICATION			SUPERSEDED	MTH		A/R			
SB 500-24-18 24SB-18	ELECTRICAL POWER - WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	DRO		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-24-20 R1 24SB-20 : REV1	ELECTRICAL POWER - OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
SB 500-24-21 24SB-21	ELECTRICAL POWER - BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
SB 500-24-22 24SB-22	ELECTRICAL POWER - SEALED LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		A/R			
SL 500-24-13 24SL-13	300 VA INVTR SHIELD	ZRH			MTH HRS	20-Jan-1983 464	A/R			Complete
SB 500-25-17 25SB-17	AFT PORTABLE SEAT INSTALLATION			SUPERSEDED	MTH	15-Aug-1971	A/R			Complete

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-25-20 25SB-20	EQUIPMENT/FURNISHINGS - STRETCHER INSTALLATION				MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-22 25SB-22	THREE PLACE SIDE FACING COUCH INSTALLATION				MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-28 R1 25SB-28 : REV1	FOUR-POINT RESTRAINT SYSTEM INSTALLATION				MTH		A/R			
OPTIONAL										
SB 500-25-31 R2 25SB-31 : REV2	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)						A/R			
SUPERSEDED										
SB 500-25-31 R3	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)						A/R			
OPTIONAL										
SL 500-25-03 25SL-3	INSPECTION/MODIFICATION OF PERSONAL FLOTATION DEVICES				MTH					
MANDATORY										
HRS										
600										
NOT APPLICABLE BY DATE OF MANUFACTURE										
SL 500-25-05 25SL-5	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION	ZRH			MTH	05-Oct-1989	A/R			Complete
INFORMATIONAL										
HRS 2605										
SL 500-25-08 25SL-08	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR	KBI			MTH	21-Jul-1998	-			Complete
HRS 3594										
SL 500-25-09 25SL-09	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT				MTH					
RECOMMENDED										
HRS										
300										
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-26-02 R1 26SB-02 : REV1	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	MYF			MTH	12-Jun-2008	A/R			Complete
HRS 4804										
SB 500-26-02 26SB-02	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	MYF			MTH	10-Jun-2005	A/R			Complete
SUPERSEDED										
HRS 4597										
ASL 500-26-02 26ASL02	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	SEE			MTH	16-Dec-2010	A/R			N/A
HRS 4935.5										
LDG 5324										
C/W ASL 500-26-02 BY INSPECTION PER MEGGITT SAFETY SYSTEMS SB 26-36 AND FOUND IT NOT APPLICABLE BY SERIAL NUMBER.										
SL 500-26-01 26SL-1	ENGINE FIRE WARNING TRAY	ICT			MTH	13-May-1982	A/R			Complete
RECOMMENDED										
HRS 318										
SB 500-27-09 27SB-9	SPEED BRAKE CONTROL SWITCH SPARE REPLACEMENT				MTH		A/R			
SUPERSEDED										
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-27-10 27SB-10	FLIGHT CONTROLS - AILERON ACTUATOR CABLE GUARD MODIFICATION	ROM			MTH	14-Aug-1984	A/R			Complete
SUPERSEDED										
HRS 1034										
SB 500-27-11 27SB-11	FLIGHT CONTROLS - FLAP BEARING AND ROLLER REPLACEMENT				MTH		A/R			
SUPERSEDED										
HRS										
SB 500-27-12 27SB-12	FLIGHT CONTROLS - RIGHT THROTTLE LEVER LOCKING CAM REPLACEMENT	LIM			MTH	04-Dec-1984	A/R			Complete
MANDATORY										
HRS 1158										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-27-13 27SB-13	FLIGHT CONTROLS - SPEED BRAKE PUSH ROD REPLACEMENT			OPTIONAL	MTH		A/R			
SB 500-27-14 27SB-14	FLIGHT CONTROLS - FLAP MOTOR CONNECTOR INSTALLATION	MYF		SUPERSEDED	MTH 02-Jul-2007 HRS 4741		A/R			Complete
SB 500-27-15 R2 27SB-15 : REV2	FLIGHT CONTROLS - FLAP GEARBOX REPLACEMENT	KBI		RECOMMENDED	MTH HRS		24 300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-27-16 27SB-16	ELEVATOR ELECTRIC TRIM ACTUATOR REPLACEMENT			RECOMMENDED	MTH HRS		300			
SB 500-27-18 27SB-18	AILERON FASTENERS INSPECTION/INSTALLATION	GJT		CANCELLED	MTH 05-Jan-2000 HRS 3802		-			Complete
SB 500-27-19 27SB-19	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION	DRO		OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-27-04 27SL-4	ELEVATOR SECTOR BRACKET RIVET INSPECTION	PBI		RECOMMENDED	MTH 13-Apr-1981 HRS 117		A/R			Complete
SL 500-27-06 27SL-6	INSPECTION OF ELEVATOR AND RUDDER TRIM SYSTEM	ZRH		MANDATORY	MTH 06-Oct-1983 HRS 716		A/R			Complete
SL 500-27-11 27SL-11	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT INSPECTION	SEE		RECOMMENDED	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		300			Complete
C/W BY INSPECTION AND FOUND OK.										
SB 500-28-07 28SB-7	FUEL - MOTIVE FLOW FUEL PRESSURE SWITCH REMOVAL	MAL		SUPERSEDED	MTH 28-Mar-1985 HRS 1255		A/R			Complete
SB 500-28-09 28SB-09	FUEL - IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY			OPTIONAL	MTH		A/R			
SB 500-28-10 R3 28SB-10 : REV3	WING FUEL CELL FOAM BLOCK REMOVAL	KBT		OPTIONAL	MTH 30-Oct-1997 HRS 3486		A/R			Complete
SB 500-28-11 28SB-11 : 500	FUEL - SURGE TANK BRACKET AND CLAMP INSTALLATION/INSPECTION	DRO		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-28-12 28SB-12	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	MYF			MTH 27-Jul-2004 HRS 4523		A/R			Complete
ASL 500-28-09 R1 28SLA09 : REV1	FUEL - TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS	PSI		MANDATORY	MTH 13-Jan-1997 HRS 3470		A/R			Complete
SL 500-28-08 R1 28SL-08 : REV1	FUEL CELL FOAM BLOCK INSTALLATION INSPECTION REQUIREMENT	KBT		MANDATORY	MTH 30-Oct-1997 HRS 3486		A/R			Complete
SL 500-29-04 29SL-4	PORTABLE HYDRAULIC SERVICE UNIT (MINI-MULE)			RECOMMENDED	MTH		A/R			
SL 500-30-06 30SL-6	EROSION SHOES FOR WING TIP PYLON LEADING EDGE, HORIZONTAL STABILIZER/VERTICAL FIN TIPS			SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-32-20 32SB-20	LANDING GEAR - STEERING CABLE PULLEY BRACKET MODIFICATION	LTN		RECOMMENDED	MTH 04-Mar-1991 HRS 2965		A/R			Complete

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-32-27 32SB-27	LANDING GEAR - GRAVEL RUNWAY MODIFICATION				MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-32-28 32SB-28	ANTI-SKID BRAKE SYSTEM INSTALLATION				MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-32-37 32SB-37	LANDING GEAR - MAIN GEAR ACTUATOR ATTACH STUD REPLACEMENT	ZRH		MANDATORY	MTH 06-Oct-1983 HRS 716		A/R			Complete
SB 500-32-38 R7 32SB-38 : REV7	BFGOODRICH BRAKES AND WHEELS INSTALLATION	ROM		OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-32-38 32SB-38	BFGOODRICH BRAKES AND WHEELS INSTALLATION	KBI		SUPERSEDED	MTH 10-Oct-1995 HRS 3410		A/R			Complete
SB 500-32-41 32SB-41	LANDING GEAR - BFG BRAKE BLEEDER BLOCK INSTALLATION AND HOSE CHANGE			SUPERSEDED	MTH		A/R			
SB 500-32-42 32SB-42	LANDING GEAR - MLG WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT	LIM		RECOMMENDED	MTH 23-Jul-1993 HRS 3367		A/R			Complete
SB 500-32-43 32SB-43	MAIN LANDING GEAR SIDE BRACE STUD INSPECTION/REPLACEMENT	EKB		RECOMMENDED	MTH 26-Jan-1995 HRS 3394		-			Complete
SB 500-32-44 32SB-44	LANDING GEAR - TRANSMITTAL OF BFGOODRICH SERVICE BULLETIN 195-183-32-1, LANDING GEAR - MAIN BRAKE SHUTTLE VALVE IMPROVEMENTS			RECOMMENDED	MTH		300			
SB 500-32-45 32SB-45	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT	KBI		RECOMMENDED	MTH 02-Feb-1998		-			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 500-32-47 R3 32SB-47 : REV3	BRAKE ASSEMBLY POSSIBLE CRACKED STATOR DISKS	SEE		MANDATORY	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		A/R			Complete
BULLETIN P.C.W. WHEN OVERHAULED BRAKES INSTALLED ON JUNE 16, 2010 UNDER MTR ID:958179										
SB 500-32-47 32SB-47 : 500	LANDING GEAR - TRANSMITTAL OF BFGOODRICH SERVICE BULLETIN 2-1530-32-2, LANDING GEAR - BRAKE ASSEMBLY POSSIBLE CRACKED STATORS	DRO		SUPERSEDED	MTH 24-Oct-2000 HRS 3992 LDG 3934		A/R			Complete
ASL 500-32-34 32SLA34	MAIN GEAR ACTUATOR TO STRUT ATTACH STUD INSPECTION	ZRH		SUPERSEDED	MTH 06-Oct-1983 HRS 716		A/R			Complete
ASL 500-32-62 32SLA62	LANDING GEAR - MAIN LANDING GEAR ACTUATOR STUD(S) INSPECTION/REPLACEMENT	KBI		MANDATORY	MTH 10-Oct-1995 HRS 3410		A/R			Complete
SL 500-32-35 32SL-35	AIR STORAGE BOTTLE	ROM		RECOMMENDED	MTH 04-May-1984 HRS 932		A/R			Complete
SL 500-32-38 32SL-38	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION	GOA		RECOMMENDED	MTH 31-Oct-1990 HRS 2927		A/R			Complete
SL 500-32-41 32SL-41	LANDING GEAR - UPLOCK ACTUATOR HYDRAULIC LINE INSPECTION	ROM		RECOMMENDED	MTH 16-Mar-1990 HRS 2738		A/R			Complete
SL 500-32-42 32SL-42	LANDING GEAR - MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION	ROM		RECOMMENDED	MTH 16-Mar-1990 HRS 2738		A/R			Complete

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-32-48 32SL-48	LANDING GEAR - LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION	LTN		RECOMMENDED	MTH 04-Mar-1991 HRS 2965		A/R			Complete
SL 500-32-53 32SL-53	LANDING GEAR - NOSE LANDING GEAR UPLOCK LINE INSPECTION	KBI		RECOMMENDED	MTH 10-Nov-1995 HRS 3430		A/R			Complete
SL 500-32-54 32SL-54	LANDING GEAR - LANDING GEAR HANDLE LOCKING SOLENOID RIGGING INSPECTION	PSI		RECOMMENDED	MTH 13-Jan-1997 HRS 3470		A/R			Complete
SL 500-32-57 R1 32SL-57 : REV1	TEIJIN GEAR SW INSP						A/R			
SL 500-32-66 32SL-66	LANDING GEAR - NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY ATTACH HARDWARE INSPECTION / REPLACEMENT	KBI		RECOMMENDED	MTH 10-Nov-1995 HRS 3430		A/R			Complete
SL 500-32-71 R1 32SL-71 : REV1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		A/R			
SL 500-32-76 32SL-76	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	SEE		MANDATORY	MTH 23-Jun-2011 HRS 4968.8 LDG 5371		A/R			Complete
C/W BY INSPECTION AND FOUND OK.										
SB 500-33-03 33SB-3	LIGHTS - WING TIP RECOGNITION LIGHT INSTALLATION			SUPERSEDED	MTH 15-Aug-1971		A/R			Complete
SB 500-33-04 33SB-4	RUDDER MOUNTED OSCILLATING BEACON INSTALLATION			SUPERSEDED	MTH 15-Aug-1971		A/R			Complete
SB 500-33-08 R6 33SB-8 : REV6	LIGHTS - RUDDER MOUNTED OSCILLATING BEACON REPLACEMENT			OPTIONAL	MTH		A/R			
SB 500-33-09 33SB-09	LIGHTS - LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION			SUPERSEDED	MTH		A/R			
SB 500-33-10 33SB-10	LIGHTS - EXIT SIGN REPLACEMENT	*CF		OPTIONAL	MTH		A/R			
SB 500-33-11 33SB-11	LIGHTS - WING TIP NAV/COLLISION LIGHT MODIFICATION			SUPERSEDED	MTH		A/R			
SB 500-33-12 33SB-12	LIGHTS - LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION			OPTIONAL	MTH		A/R			
SB 500-33-13 R1 33SB-13 : REV1	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL	MTH		A/R			
SB 500-33-14 33SB-14	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
SL 500-33-04 33SL-04	LIGHTS - LANDING LIGHT SWITCH INSPECTION/REPLACEMENT	KBI		SUPERSEDED	MTH 19-Dec-1994 HRS 3393		A/R			Complete
SB 500-34-07 34SB-7	NAVIGATION - INSTALLATION OF COLLINS RADIO ALTIMETER			SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-34-15 34SB-15	9500 POUND ZERO FUEL WEIGHT INSTALLATION	ICT		SUPERSEDED	MTH 29-Sep-1982 HRS 353		A/R			Complete



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
<i>SB 500-34-29</i> <i>34SB-29</i>	NAVIGATION - AREA NAVIGATION ADAPTER CABLE INSTALLATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-34-31</i> <i>34SB-31</i>	NAVIGATION - INSTALLATION OF ANGLE-OF-ATTACK SYSTEM			SUPERSEDED	MTH 15-Aug-1971		A/R			Complete
<i>SB 500-34-32</i> <i>34SB-32</i>	NAVIGATION - AREA NAV (RNS-3500) SYSTEM INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<i>SB 500-34-40</i> <i>34SB-40</i>	NAVIGATION - MARKER BEACON LAMP DIMMING			SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-34-45</i> <i>34SB-45</i>	POINTER SENTRY ELT INSTALLATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-34-49</i> <i>34SB-49</i>	NAVIGATION - VLF SYSTEM H-FIELD LOOP ANTENNA INSTALLATION			OPTIONAL	MTH		A/R			
<i>SB 500-34-57</i> <i>34SB-57</i>	NAVIGATION - STARTER-GENERATOR AND GCU FILTER INSTALLATION	UBI		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>ASB 500-34-58 R1</i> <i>34SBA58 : REV1</i>	NAVIGATION - VG14A VERTICAL GYRO INSPECTION	ROM		MANDATORY	MTH 16-Mar-1990 HRS 2738		A/R			Complete
<i>SB 500-34-59 R1</i> <i>34SB-59 : REV1</i>	NAVIGATION - VN-212 SIGNAL GROUND WIRING MODIFICATION			OPTIONAL	MTH		A/R			
<i>SB 500-34-64</i> <i>34SB-64</i>	NAVIGATION - HONEYWELL RADIO ALTIMETER MODEL RT-300 INSTALLATION			OPTIONAL	MTH		A/R			
<i>SB 500-34-65</i> <i>34SB-65</i>	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION			OPTIONAL	MTH		A/R			
<i>SB 500-34-66</i> <i>34SB-66</i>	NAVIGATION - SANDEL TERRAIN AWARENESS WARNING SYSTEM (TAWS) INSTALLATION			OPTIONAL	MTH		A/R			
<i>SB 500-34-67</i> <i>34SB-67</i>	NAVIGATION - SIGMA-TEK CONTROL PANEL INSTALLATION			OPTIONAL	MTH		A/R			
<i>SL 500-34-32</i> <i>34SL-32</i>	FLIGHT DIRECTOR - BACK COURSE LIMITATION	ZRH		RECOMMENDED	MTH 30-May-1983 HRS 597		A/R			Complete
<i>SL 500-34-37</i> <i>34SL-37</i>	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION			RECOMMENDED	MTH		A/R			
<i>SB 500-35-04</i> <i>35SB-4</i>	OXYGEN - INSTALLATION OF 64 CUBIC FOOT OXYGEN SYSTEM			SUPERSEDED	MTH		A/R			
<i>SB 500-35-06 R1</i> <i>35SB-06 : REV1</i>	OXYGEN - EROS OXYGEN MASK INSTALLATION			OPTIONAL	MTH		A/R			
<i>SB 500-35-06</i> <i>35SB-06</i>	OXYGEN - EROS OXYGEN MASK INSTALLATION			SUPERSEDED	MTH		A/R			
<i>SL 500-35-06</i> <i>35SL-06</i>	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			New Req

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-36-04 36SB-04	PNEUMATIC - ENGINE BLEED AIR CONNECTOR IMPROVEMENT			OPTIONAL	MTH		A/R			
SB 500-36-05 R1 36SB-05 : REV1	PNEUMATIC - DOOR SEAL VALVE REPLACEMENT			OPTIONAL	MTH		A/R			
SB 500-52-14 R1 52SB-14 : REV1	CBN DOOR STEP HINGE	ZRH			MTH 06-Oct-1983 HRS 716		A/R			Complete
SB 500-52-14 52SB-14	CBN DOOR STEP HINGE	ZRH		SUPERSEDED	MTH 06-Oct-1983 HRS 716		A/R			Complete
SB 500-52-15 52SB-15	DOORS - CABIN DOOR HINGE PIN AND NEEDLE BEARING REPLACEMENT AND LUBE FITTING INSTALLATION	ZRH		OPTIONAL	MTH 21-Apr-1989 HRS 2435		A/R			Complete
SB 500-52-16 52SB-16	DOORS - ENTRY STEP ASSEMBLY IMPROVEMENT	UBI		SUPERSEDED	MTH HRS		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-52-18 52SB-18	DOOR - BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION	UBI		SUPERSEDED	MTH HRS		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-52-19 52SB-19	DOORS - ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP)	*CF		RECOMMENDED	MTH HRS		300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME.										
ASL 500-52-04	DOORS - EMERGENCY EXIT INSPECTION			MANDATORY	DAYS HRS		365 600		12-Jan-2012 5538.93	5 m 2 d 557.93
SB 500-53-03 53SB-3	FUSELAGE - DRAG CHUTE INSTALLATION			SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-53-13 53SB-13	FUSELAGE - TAILCONE SKIN - INSPECTION AND MODIFICATION OF VERTICAL FIN SPAR INTERFERENCE	ROM		SUPERSEDED	MTH 04-May-1984 HRS 932		A/R			Complete
SB 500-53-14 53SB-14	NOSE DRIP CAP INSTALLATION	ZRH		OPTIONAL	MTH 20-Jan-1983 HRS 464		A/R			Complete
SB 500-53-20 53SB-20	FUSELAGE - FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION	*CF		RECOMMENDED			A/R			
SB 500-53-22 53SB-22	FUSLEAGE - DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT			OPTIONAL	MTH		A/R			
SB 500-53-23 53SB-23	AN3-5A BOLT INSPECTION/REPLACEMENT	KBI		RECOMMENDED	MTH HRS		24 300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-53-26 53SB-26	FUSELAGE - WHEEL WELL BOX IMPROVEMENT	DRO		OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-53-01 53SL-1	NOSE BAGGAGE AND TAILCONE ACCESS DOOR LATCHES	KBI		MANDATORY	MTH 19-Dec-1994 HRS 3393		A/R			Complete
SL 500-53-05 R1 53SL-05 : REV1	FUSELAGE - INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED			A/R			
SB 500-55-04 55SB-4	STABILIZERS - VERTICAL FIN FORWARD SPAR MODIFICATION			SUPERSEDED	MTH HRS		1			

NOT APPLICABLE-WEAR DOES NOT EXCEED LIMITS PRESENTED IN SB53-13 OR SB550-53-6



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-55-01 R1 <i>55SL-01 : REV1</i>	TORQUE TUBE INSP	LTN			MTH 04-Mar-1991 HRS 2965		A/R			Complete
SB 500-56-06 <i>56SB-6</i>	WINDOWS - WINDSHIELD SPARES REPLACEMENT	KBI		SUPERSEDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-57-04 <i>57SL-04</i>	WIRE BUNDLE ROUTING IMPROVEMENT	PSI		RECOMMENDED	MTH 13-Jan-1997 HRS 3470		A/R			Complete
SL 500-71-07 <i>71SL-7</i>	ENGINE WIRE BUNDLE INSPECTION	ZRH		RECOMMENDED	MTH 30-May-1983 HRS 597		A/R			Complete
SL 500-71-09 <i>71SL-9</i>	ENGINE BLEED AIR LINE RETAINER INSPECTION	ZRH		RECOMMENDED	MTH 30-May-1983 HRS 597		A/R			Complete
SL 500-72-03 <i>72SL-3</i>	ENGINE - JT15D FAN BLADE INSPECTION	ZRH			MTH 16-Feb-1988 HRS 2120		A/R			Complete
SL 500-72-04 <i>72SL-04</i>	ENGINE - INTRODUCTION OF NEW IMPROVED GAS GENERATOR CASE			RECOMMENDED	MTH HRS		150			
P&WC SB 7286 REV2 RECOMMENDS ACCOMPLISHMENT AT ENGINE OVERHA UL AFTER 5-04-90.										
SL 500-72-10	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN JT15D-72-7590, TURBOFAN ENGINE BORESCOPE INSPECTION OF IMPELLER REAR FACE AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) C03001R1			RECOMMENDED	MTH	19	A/R			
LEFT ENGINE <i>72SL-10 : E1**L</i>										
SL 500-72-10	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN JT15D-72-7590, TURBOFAN ENGINE BORESCOPE INSPECTION OF IMPELLER REAR FACE AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) C03001R1			RECOMMENDED	MTH	19	A/R			
RIGHT ENGINE <i>72SL-10 : E2**R</i>										
SB 72-7459 R1 <i>E1</i>	REPLACEMENT OF IGNITER			OPTIONAL			A/R			
SB 72-7459 R1 <i>E2</i>	REPLACEMENT OF IGNITER			OPTIONAL			A/R			
SB 72-7625 R1 <i>E1</i>	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
SB 72-7625 R1 <i>E2</i>	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
SB 500-74-01 <i>74SB-1</i>	IGNITION - DUAL IGNITION EXCITER BOX INSTALLATION			OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-74-02 <i>74SL-2</i>	IMPROVED ENGINE EXCITER BOX			RECOMMENDED	MTH		A/R			
SL 500-74-04 <i>74SL-04</i>	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF			RECOMMENDED	MTH HRS		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-77-02 <i>77SB-2</i>	VERTICAL SCALE INSTRUMENTS SEPARATION			SUPERSEDED	MTH		A/R			
SB 500-78-01 <i>78SB-1</i>	EXHAUST - THRUST REVERSER INSTALLATION			SUPERSEDED	MTH 15-Aug-1971		A/R			Complete
SB 500-78-11 <i>78SB-11</i>	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION	KBI		RECOMMENDED	MTH 19-Dec-1994 HRS 3393		A/R			Complete
SB 500-78-12 <i>78SB-12 : 500</i>	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT	DRO		OPTIONAL	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-78-11 LEFT ENGINE <i>78SL-11</i>	THRUST REVERSER INBOARD STANG MODIFICATION	LIM		OPTIONAL	MTH 23-Jul-1993 HRS 3367		A/R			Complete
SL 500-78-11 RIGHT ENGINE <i>78SL-11</i>	THRUST REVERSER INBOARD STANG MODIFICATION	LIM		OPTIONAL	MTH 23-Jul-1993 HRS 3367		A/R			Complete
SL 500-78-12 <i>78SL-12</i>	THRUST REVERSER JUNCTION BOX MODIFICATION	KBI		RECOMMENDED	MTH 02-Feb-1999 HRS 3651		A/R			Complete
SL 500-78-13 <i>78SL-13</i>	THRUST REVERSER OPERATIONAL TEST	LTN		SUPERSEDED	MTH 04-Mar-1991 HRS 2965		A/R			Complete
SL 500-78-16 <i>78SL-16</i>	EXHAUST - THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT (ROHR INC. SERVICE BULLETIN NO. CIT 78-11)			RECOMMENDED	MTH HRS		300			
SB 500-80-05 <i>80SB-05</i>	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB	DRO		OPTIONAL	MTH		A/R			

OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 1998-04-38 <i>30AD-02</i>	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS BY PROVIDING MORE CLEARLY DEFINED PROCEDURES AND LIMITATIONS ASSOCIATED WITH SUCH CONDITIONS	KBI		MANDATORY	MTH 21-Jul-1998 HRS 3594		-			Complete
AD 2001-23-17 <i>34AD-26</i>	GNS 430 UNITS, PART NUMBER 011-00280-00; REFER TO AD FOR SERIAL NUMBER EFFECTIVITY.	DRO		MANDATORY	MTH 20-May-2004 HRS 4506		-			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2006-04-10 <i>26AD-02</i>	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	MYF			MTH 16-May-2006 HRS 4670		-			Complete
AD 1990-07-10 R1 <i>21AD-01</i>	FREON AIR CONDITIONERS INSTALLED IN THE AFT SECTION OF THE BAGGAGE COMPARTMENT.	GOA		MANDATORY	MTH 31-Oct-1990 HRS 2927		-			Complete
AD 1995-25-10 <i>21AD-02</i>	REPLACE THE OUTFLOW SAFETY VALVE IN ACCORDANCE WITH ALLIED SIGNAL SERVICE BULLETIN 103576-21-4056.	KBI		MANDATORY	MTH 12-Mar-1996 HRS 3434		-			Complete
AD 1983-01-06 <i>25AD-1</i>	TO DETECT LIFE PRESERVERS AND FLOTATION DEVICES WHICH HAVE CO2 INFLATION VALVE MANIFOLDS THAT MAY OPERATE IMPROPERLY, AND TO CORRECT THE DEFICIENCY, PERFORM THE FOLLOWING IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2, OF SWITLIK PARACHUTE COMPANY, INC., SERVICE BULLETIN 25-00-16, DATED APRIL 1, 1982:	ZRH			MTH 09-Jun-1986 HRS 1713		-			Complete
AD 1989-06-01 <i>25AD-02</i>	PREVENT THE IMPROPER FUNCTIONING OF THE CARBON DIOXIDE (CO2) INFLATORS ON TSO-C13, LIFE PRESERVERS AND TSO-C72 INDIVIDUAL FLOTATION DEVICES	ZRH		MANDATORY	MTH 05-Oct-1989 HRS 2605		-			Complete
AD 1998-25-10 <i>25AD-03</i>	SEAT RESTRAINT SYSTEM	KBI		MANDATORY	MTH 29-Jul-1999 HRS 3664		A/R			Complete
AD 2007-11-17 <i>26AD-03</i>	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES	MYF		MANDATORY	MTH 02-Jul-2007 HRS 4741		A/R			Complete
AD 2010-04-16 (G) <i>26AD-06</i>	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	SEE		MANDATORY	DAYS 16-Dec-2010 HRS 4935.5 LDG 5324		A/R			N/A
AD IS N/A. BOTTLE INSTALLED IS MANUFACTURED BY AMEREX.										
AD 2010-04-16 <i>26AD-06</i>	TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY	MTH 16-Dec-2010 HRS 4935.5 LDG 5324		A/R			N/A
AD IS N/A. BOTTLE INSTALLED IS MANUFACTURED BY AMEREX.										
AD 2006-06-03 <i>28AD-01</i>	PREVENT FUEL VAPOR IGNITION	MYF		MANDATORY	MTH 16-May-2006 HRS 4670		-			Complete
AD 1998-25-02 <i>34AD-22</i>	TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS WITH A TOP-MOUNTED ANTENNA, WHICH COULD RESULT IN THE PILOT MAKING AN INCORRECT INITIAL MANEUVER BASED ON THE DISPLAYED INFORMATION WHILE TRYING TO VISUALLY ACQUIRE THE AIRCRAFT.	KBI		MANDATORY	MTH 29-Jul-1999 HRS 3664		-			Complete



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 2003-13-08 <i>34AD-27</i>	GOODRICH AVIONICS SYSTEMS, INC. TAWS8000 TERRAIN AWARENESS WARNING SYSTEM	DRO		MANDATORY	MTH 05-Aug-2003 HRS 4440		-			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2006-16-18 <i>34AD-35</i>	PREVENT A BEARING ERROR	MYF		SUPERSEDED	MTH 11-Dec-2006 HRS 4712		-			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 1994-19-06 <i>35AD-04</i>	TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING INTO THE AFFECTED CREW OXYGEN MASKS.	KBI		MANDATORY	MTH 15-May-1995 HRS 3401		-			Complete
AD 1999-08-21 <i>35AD-02</i>	PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS	DRO		MANDATORY	MTH 24-Oct-2000 HRS 3992		-			Complete
AD 1974-08-09 R2 <i>38AD-01</i>	WASTE RECEPTACLE INSPECTION	CAE			MTH 08-Oct-1999 HRS 3715		-			Complete
AD 72-1 <i>72AD-04 : E1**L</i>	JT15D FAN BLADE INSP	ZRH			MTH 16-Feb-1988 HRS 2120		-			Complete
AD 1993-18-08 <i>72AD-04 : E1**L</i>	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	KBI		MANDATORY	MTH 30-Oct-1997 HRS 3486		-			Complete
AD 1993-18-08 <i>72AD-04 : E2**R</i>	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	KBI		MANDATORY	MTH 30-Oct-1997 HRS 3486		-			Complete
AD 2004-04-09 <i>72AD-05 : E1**L</i>	TO PREVENT UNCONTAINED FAILURE OF THE IMPELLER AND POSSIBLE DAMAGE TO THE AIRPLANE	MYF		MANDATORY	MTH 16-May-2006 HRS 4670 LDG 5004		-			Complete
AD 2004-04-09 <i>72AD-05 : E2**R</i>	TO PREVENT UNCONTAINED FAILURE OF THE IMPELLER AND POSSIBLE DAMAGE TO THE AIRPLANE	DRO		MANDATORY	MTH 24-May-2004 HRS 4506 LDG 4926		-			Complete
NOT APPLICABLE BY COMPONENT PART NUMBER.										
AD 1993-05-15 <i>78AD-01</i>	TO PREVENT SEVERELY REDUCED CONTROLLABILITY OF ENGINE POWER AUTHORITY.	KBI		MANDATORY	MTH 15-May-1995 HRS 3401		A/R			Complete
AD 2004-08-15 <i>34AD-28</i>	PREVENT THE LOADING OF THE BARO SET POTENTIOMETER, WHICH COULD RESULT IN AN UNACCEPTABLE ALTITUDE ERROR.	MYF			MTH 29-Mar-2005 HRS 4589		A/R			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2004-09-05 <i>32AD-01</i>	PREVENT JAMMING OF THE WHEEL/TIRE ASSEMBLY	DRO			MTH 20-May-2004 HRS 4506 LDG 4826		-			Complete
NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**
 Aircraft Model: **501 - MODEL 501**
 Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**
 Airworthiness: **12-Sep-1980**
 Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
21FO-05A <i>21FO-05 : A</i>	RH FAN INSTALLATION FORWARD DIVIDER FACTORY OPTION	*CF		180A FO	MTH 12-Sep-1980		-			
24FO-01B <i>24FO-01 : B</i>	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION	*CF		12B FO	MTH 12-Sep-1980		-			
25FO-04	MAP CASE FACTORY OPTION	*CF		103 FO	MTH 12-Sep-1980		-			
25FO-05	STORAGE DRAWER RIGHT HAND LOUNGE FACTORY OPTION	*CF		104 FO	MTH 12-Sep-1980		-			
25FO-07	SEATING OPT STANDARD FACTORY OPTION	*CF		109 FO	MTH 12-Sep-1980		-			
25FO-18	JUMP SEAT-AFT BAGGAGE COMPARTMENT FACTORY OPTION	*CF		121 FO	MTH 12-Sep-1980		-			
25FO-20G <i>25FO-20 : G</i>	EXECUTIVE TABLE USED W/STD & OPT A FACTORY OPTION	*CF		124G FO	MTH 12-Sep-1980		-			
25FO-21	REFRESHMENT CENTER FACTORY OPTION	*CF		128 FO	MTH 12-Sep-1980		-			
25FO-25A <i>25FO-25 : A</i>	CARPET RUNNER CABIN AISLE FACTORY OPTION	*CF		136A FO	MTH 12-Sep-1980		-			
25FO-37	CHIMES UNIT FACTORY OPTION	*CF		166 FO	MTH 12-Sep-1980		-			
25FO-38	AFT FOLDING DOOR FACTORY OPTION	*CF		184 FO	MTH 12-Sep-1980		-			
31FO-02B <i>31FO-02 : B</i>	CLOCK DIGITAL ELECTRIC 24 HOUR LH FACTORY OPTION	*CF		182B FO	MTH 12-Sep-1980		-			
32FO-02	BRAKES EXTENDED LIFE FACTORY OPTION	*CF		93 FO	MTH 12-Sep-1980		-			
33FO-02B <i>33FO-02 : B</i>	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH 12-Sep-1980		-			
33FO-03	LIGHT-ROTATING BEACON RUDDER MOUNTED FACTORY OPTION	*CF		51 FO	MTH 12-Sep-1980		-			
34FO-02	INDICATOR-ANGLE OF ATTACK FACTORY OPTION	*CF		11 FO	MTH 12-Sep-1980		-			
34FO-07D <i>34FO-07 : D</i>	2ND TRANSPONDER-COLLINS TDR-90 FACTORY OPTION	*CF		623D FO	MTH 12-Sep-1980		-			
34FO-09P <i>34FO-09 : P</i>	RADAR RDR-1100 COLOR EXCH FACTORY OPTION	*CF		628P FO	MTH 12-Sep-1980		-			
34FO-14	AA215 RAD ALTIMETER W/SEPARATE INDICATOR FACTORY OPTION	*CF		672 FO	MTH 12-Sep-1980		-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **FALCON AVIATION LTD.**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0166** Unit: **0559** Reg No: **N166FA**

Airworthiness: **12-Sep-1980**

Print Date: **10-Aug-2011 1:13PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	4981	5391	01-Aug-2011	.22
ENG 1	4905.1	5294	01-Aug-2011	.23
ENG 2	4952.1	5341	01-Aug-2011	.23

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
34FO-15	FLIGHT DIRECTOR LH-4" SINGLE CUE SPERRY FACTORY OPTION	*CF		679 FO	MTH 12-Sep-1980		-			
34FO-18H <i>34FO-18 : H</i>	AREA NAVIGATION BENDIX RNS3500 FACTORY OPTION	*CF		687H FO	MTH 12-Sep-1980		-			
73FO-01C <i>73FO-01 : C</i>	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION	*CF		76C FO	MTH 12-Sep-1980		-			
78FO-01	THRUST REVERSERS FACTORY OPTION	*CF		193 FO	MTH 12-Sep-1980		-			